



**UNITED STATES
NUCLEAR REGULATORY COMMISSION**
REGION III
2443 WARRENVILLE ROAD, SUITE 210
LISLE, IL 60532-4352

September 1, 2011

Mr. Michael J. Pacilio
Senior Vice President, Exelon Generation Company, LLC
President and Chief Nuclear Officer (CNO), Exelon Nuclear
4300 Winfield Road
Warrenville, IL 60555

SUBJECT: MID-CYCLE LETTER FOR LASALLE COUNTY STATION, UNITS 1 AND 2;
05000373/2011-006; 05000374/2011-006

Dear Mr. Pacilio:

On August 10, 2011, the NRC completed its mid-cycle performance review of the LaSalle County Station, Units 1 and 2. The NRC reviewed the most recent quarterly performance indicators (PIs) in addition to inspection results and enforcement actions from July 1, 2010, through June 30, 2011. This letter informs you of the NRC's assessment of your facility during this period and its plans for future inspections at your facility. This performance review and enclosed inspection plan do not include security information. A separate letter will include the NRC's assessment of your performance in the Security Cornerstone and its security-related inspection plan.

The NRC determined the performance at the LaSalle County Station, Units 1 and 2, during the most recent quarter was within the Licensee Response Column of the NRC's Reactor Oversight Process (ROP) Action Matrix because all inspection findings had very low (i.e. green) safety significance and all PIs indicated that your performance was within the normal, expected range (i.e., green). Therefore, the NRC plans to conduct ROP baseline inspections at your facility.

The enclosed inspection plan details the inspections, less those related to physical protection, scheduled through December 31, 2012. Routine resident inspections are not included in the inspection plan. In addition to the ROP baseline inspections, the NRC will be conducting the following additional inspection at your facility: IP 60855.1, "Operation of an Independent Spent Fuel Storage Installation (ISFSI) at Operating Plants." The inspections listed during the last nine months of the inspection plan are tentative and may be revised at the end-of-cycle performance review. The NRC provides the inspection plan to allow for the resolution of any scheduling conflicts and personnel availability issues. The NRC will contact you as soon as possible to discuss changes to the inspection plan should circumstances warrant any changes.

In the days following the Fukushima Daiichi nuclear accident in Japan, the Commission directed the staff to establish a senior-level agency task force to conduct a methodical and systematic review of the NRC's processes and regulations to determine whether the agency should make additional improvements to its regulatory system. The NRC has since completed Temporary Instruction (TI) 183, "Follow-up to Fukushima Daiichi Nuclear Station Fuel Damage Event," and TI-184, "Availability and Readiness Inspection of Severe Accident Management Guidelines (SAMGs)" at your facility. Results of these inspections can be found here: <http://www.nrc.gov/japan/japan-activities.html>. Additionally, on May 11, 2011, the agency issued NRC Bulletin 2011-01, "Mitigating Strategies," to confirm compliance with Order EA-02-026, subsequently imposed license conditions, and 10 CFR 50.54(hh)(2), and to determine the status of licensee mitigating strategies programs. On July 12, 2011, the NRC's Task Force made its recommendations to the Commission in its report, "Recommendations for Enhancing Reactor Safety in the 21st Century: The Near-Term Task Force Review of Insights from the Fukushima Daiichi Accident." The NRC is currently reviewing the Task Force's recommendations to determine what additional actions may be warranted.

In accordance with 10 CFR 2.390 of the NRC's "Rules of Practice," a copy of this letter will be available electronically for public inspection in the NRC Public Document Room or from the Publicly Available Records (PARS) component of NRC's document system (ADAMS). ADAMS is accessible from the NRC Website at <http://www.nrc.gov/reading-rm/adams.html> (the Public Electronic Reading Room).

Please contact me at (630) 829-9628 with any questions you may have regarding this letter.

Sincerely,

/RA/

Kenneth Riemer, Branch Chief
Branch 2
Division of Reactor Projects

Docket Nos. 50-373; 50-374
License Nos. NPF-11; NPF-18

Enclosure: LaSalle County Station, Units 1 and 2, Inspection/Activity Plan

cc w/encl: Distribution via ListServe

In the days following the Fukushima Daiichi nuclear accident in Japan, the Commission directed the staff to establish a senior-level agency task force to conduct a methodical and systematic review of the NRC's processes and regulations to determine whether the agency should make additional improvements to its regulatory system. The NRC has since completed Temporary Instruction (TI) 183, "Follow-up to Fukushima Daiichi Nuclear Station Fuel Damage Event," and TI-184, "Availability and Readiness Inspection of Severe Accident Management Guidelines (SAMGs)" at your facility. Results of these inspections can be found here: <http://www.nrc.gov/japan/japan-activities.html>. Additionally, on May 11, 2011, the agency issued NRC Bulletin 2011-01, "Mitigating Strategies," to confirm compliance with Order EA-02-026, subsequently imposed license conditions, and 10 CFR 50.54(hh)(2), and to determine the status of licensee mitigating strategies programs. On July 12, 2011, the NRC's Task Force made its recommendations to the Commission in its report, "Recommendations for Enhancing Reactor Safety in the 21st Century: The Near-Term Task Force Review of Insights from the Fukushima Daiichi Accident." The NRC is currently reviewing the Task Force's recommendations to determine what additional actions may be warranted.

In accordance with 10 CFR 2.390 of the NRC's "Rules of Practice," a copy of this letter will be available electronically for public inspection in the NRC Public Document Room or from the Publicly Available Records (PARS) component of NRC's document system (ADAMS). ADAMS is accessible from the NRC Website at <http://www.nrc.gov/reading-rm/adams.html> (the Public Electronic Reading Room).

Please contact me at (630) 829-9628 with any questions you may have regarding this letter.

Sincerely,

/RA/

Kenneth Riemer, Branch Chief
Branch 2
Division of Reactor Projects

Docket Nos. 50-373; 50-374
License Nos. NPF-11; NPF-18

Enclosure: LaSalle County Station, Units 1 and 2, Inspection/Activity Plan
cc w/encl: Distribution via ListServe

DISTRIBUTION:

See next page

DOCUMENT NAME: G:\DRPIII\1-Secy\1-Work In Progress\2011 MOC Letters\LaSalle MOC Letter 2011.docx

Publicly Available Non-Publicly Available Sensitive Non-Sensitive

To receive a copy of this document, indicate in the concurrence box "C" = Copy without attach/encl

"E" = Copy with attach/encl "N" = No copy

OFFICE	RIII	RIII	N	RIII	RIII
NAME	MZiolkowski	KRiemer:cs			
DATE	08/19/11	08/22/11			

OFFICIAL RECORD COPY

Letter to M. Pacilio from K. Riemer dated September 1, 2011

SUBJECT: MID-CYCLE LETTER FOR LASALLE COUNTY STATION, UNITS 1 AND 2;
05000373/2011-006; 05000374/2011-006

DISTRIBUTION:

Daniel Merzke

RidsNrrDorLpl3-2 Resource

RidsNrrPMLaSalle

RidsNrrDirslrib Resource

Cynthia Pederson

Steven Orth

Jared Heck

Allan Barker

Carole Ariano

Linda Linn

DRPIII

DRSIII

Patricia Buckley

Tammy Tomczak

ROPAssessment.Resource@nrc.gov

LaSalle
Inspection / Activity Plan
09/01/2011 - 12/31/2012

Planned Dates		Inspection Activity	Title	No. of Staff on Site
Start	End			
		BI RP - RADIATION PROTECTION BASELINE INSPECTION		1
09/26/2011	09/30/2011	IP 2515/179	Verification of Licensee Responses to NRC Requirement for Inventories of Materials Tracked in NSTS	
09/26/2011	09/30/2011	IP 71124.05	Radiation Monitoring Instrumentation	
		BI FIRE - FIRE PROTECTION INSPECTION & BAG TRIP		3
10/17/2011	11/18/2011	IP 7111105T	Fire Protection [Triennial]	
		BI RP - RADIATION PROTECTION BASELINE INSPECTION		1
10/31/2011	11/04/2011	IP 71124.01	Radiological Hazard Assessment and Exposure Controls	
10/31/2011	11/04/2011	IP 71151	Performance Indicator Verification	
		BI OLRQ - BIENNIAL REQUAL PROGRAM INSPECTION		2
11/14/2011	11/18/2011	IP 7111111B	Licensed Operator Requalification Program	
		BI ISI - INSERVICE INSPECTION - UNIT 1		1
02/13/2012	02/17/2012	IP 7111108G	Inservice Inspection Activities - BWR	
		BI RP - RADIATION PROTECTION BASELINE INSPECTION		1
02/20/2012	02/24/2012	IP 71124.01	Radiological Hazard Assessment and Exposure Controls	
02/20/2012	02/24/2012	IP 71124.02	Occupational ALARA Planning and Controls	
		BI RP - RADIATION PROTECTION BASELINE INSPECTION		1
05/07/2012	05/11/2012	IP 71124.06	Radioactive Gaseous and Liquid Effluent Treatment	
05/07/2012	05/11/2012	IP 71151-PR01	RETS/ODCM Radiological Effluent	
		ISFSI - ISFSI INSPECTION - SCHEDULE DEPENDENT		1
05/01/2012	07/31/2012	IP 60855.1	Operation of an Independent Spent Fuel Storage Installation at Operating Plants	
		BI HS - TRIENNIAL HEAT SINK INSPECTION		2
07/16/2012	07/20/2012	IP 7111107T	Heat Sink Performance	
		TI-177 - TI-2515/177 - GAS VOIDING IN ECCS PIPING		2
07/30/2012	08/17/2012	IP 2515/177	Managing Gas Accumulation In Emergency Core Cooling, Decay Heat Removal & Containment Spray System	
		BI EPX - EP EXERCISE INSPECTION / PI VERIFICATION		2
07/30/2012	08/03/2012	IP 7111401	Exercise Evaluation	
07/30/2012	08/03/2012	IP 71151	Performance Indicator Verification	
		OL PREP - LASALLE INIT PREP - 09/2012		3
09/03/2012	09/07/2012	W90267	OL - INITIAL EXAM - 2012 SEPT/OCT - LASA	
		BI MODS - TRIENNIAL PERM MODS/50.59		3
09/10/2012	09/28/2012	IP 7111117T	Evaluations of Changes, Tests, or Experiments and Permanent Plant Modifications	
		BI RP - RADIATION PROTECTION BASELINE INSPECTION		1
09/24/2012	09/28/2012	IP 71124.08	Radioactive Solid Waste Processing and Radioactive Material Handling, Storage, and Transportation	

LaSalle
Inspection / Activity Plan
09/01/2011 - 12/31/2012

Planned Dates		Inspection Activity	Title	No. of Staff on Site
Start	End			
BI RP - RADIATION PROTECTION BASELINE INSPECTION				
09/24/2012	09/28/2012	IP 71151-BI01	Reactor Coolant System Activity	1
OL EXAM - LASALLE INIT EXAM - 09/2012				
09/24/2012	10/05/2012	W90267	OL - INITIAL EXAM - 2012 SEPT/OCT - LASA	3
BI RP - RADIATION PROTECTION BASELINE INSPECTION				
12/10/2012	12/14/2012	IP 71124.03	In-Plant Airborne Radioactivity Control and Mitigation	1
12/10/2012	12/14/2012	IP 71124.04	Occupational Dose Assessment	
12/10/2012	12/14/2012	IP 71151-OR01	Occupational Exposure Control Effectiveness	