
Open Generic Communication TACs (PA No. 115126CA/B)
Summary Report (AS OF 08/31/2011)

TAC NO.	TAC TITLE	STATUS	AGE (Mon)	TAC OPENED	LEAD ORG
ME4841	RIS 'Adequacy of Station Electric Distribution System Voltages'	O	11.0	10/08/2010	DE
ME5167	RIS 'Staff Position on the Clarification of Submitting of Alter. Under 10 CFR 50.55'	O	9.0	12/13/2010	DCI
ME5784	RIS 'Selecting Edition and Addenda of Section XI of ASME Code for Part 52 Inspection Programs'	O	6.0	03/07/2011	NRO
ME5921	RIS 'NRC Staff Position on Use of Current-Generation AREVA PWR Safety Analysis Methods'	O	6.0	03/29/2011	DSS
ME6022	RIS 'Guidance on Meeting NRC Expectations for Generic Letter 96-05'	O	5.0	04/13/2011	DCI
ME6255	RIS 'Metal Fatigue Analysis Performed By Computer Software'	O	4.0	05/17/2011	DLR
ME6601	RIS 'Clarification for Updating Protective Action Recommendations'	O	3.0	06/29/2011	NSIR
ME6641	RIS 'Clarification of Methods For Applicant And Vendor Compliance With Part 21'	O	2.0	07/05/2011	NMSS
ME6862	RIS 'Endorsement of NEI Guidance Addendum for Managing Personnel Fatigue at Power Reactor Sites'	O	1.0	08/15/2011	DIRS
ME6890	RIS 'NRC Staff Position on Applying SRs 3.0.2 & 3.0.3 to Administrative Controls Program'	O	1.0	08/22/2011	DIRS

Open Generic Communication TACs (PA No. 115126CA/B)
Summary Report (AS OF 08/31/2011)

TAC NO.	TAC TITLE	STATUS	AGE (Mon)	TAC OPENED	LEAD ORG
ME4076	IN 'Non-Conservatisms with Spent Fuel Pool Criticality Analyses'	O	15.0	06/16/2010	DPR
ME5927	IN 'Licensee Event Reports Containing Information Pertaining to Defects to Basic Components'	O	6.0	03/29/2011	IOEB
ME6225	IN 'Issues Identified During NRC Post-Approval Site Inspections For License Renewal'	O	4.0	05/11/2011	DLR
ME6308	IN 'Concrete Degradation By Alkali-Silica Reaction'	O	4.0	05/25/2011	DLR
ME6390	IN 'Potentially Nonconservative Screening Value For Dam Failure Frequency In PRA'	O	3.0	06/09/2011	DRA
ME6791	IN 'Instrumentation & Control Modules – Failures, Incorrect Configurations with Part 21'	O	1.0	08/02/2011	DIRS
ME6847	IN 'Hydrology Study Affects Design Basis External Flooding Evaluation'	O	1.0	08/12/2011	DE
ME6848	IN 'Seismic Issues Involving Safety-Related Tanks'	O	1.0	08/12/2011	DIRS
ME3680	GL 'Potential Embrittlement of Fuel Rods During a Postulated Loss-of-Coolant Accident'	O	17.0	04/01/2010	DSS
ME5720	GL 'Implications of Updated Probabilistic Seismic Hazard Estimates in Central and Eastern US of Existing Plants'	O	7.0	02/22/2011	DPR
ME6167	BL '10 CFR 50.54(hh)(2) Mitigating Strategies'	O	4.0	05/05/2011	DPR