



Br. 1

August 31, 2011

Mr. Héctor Bermúdez
U.S. Nuclear Regulatory Commission, Region 1
Medical Branch
Division of Nuclear Materials Safety
475 Allendale Road
King of Prussia
Pennsylvania 19406-1415

RECEIVED
REGION 1
2011 SEP -8 AM 10:56

RE: Byproduct Materials
License Number 52-15139-01
Control Number 574789 (Reference)
03008181
NO. RET

Dear Mr. Bermúdez:

As requested in your letter dated June 9, 2011, addressed to me, I am enclosing copies of the close-out wipe test and radiation level surveys of the old location prior to release for unrestricted use.

Please advice on any additional information that may be required.

Cordially,

José Luis Rodríguez, MHSA
Executive Director

575965
NMSS/RGN1 MATERIALS-002

Last

WIPE TEST SURVEY RECORD

Nuclear Medicine Facilities
@ 2nd floor

Date : 7/19/2011

Instrument used : Victoreen DWTC
Model 05-578

Sample No.	LOCATION	NET dpm
1.	Counter Gamma Camera Varian	Pass
2.	Gamma Camera Varian	"
3.	Gamma Camera Helix	"
4.	Counter Gamma Camera Helix	"
5. Hot Room	Counter Lead Crystal	"
6.	Sink	"
7.	Counter top in front of Nest	"
8.	Nest	"
9.		
10.		
11.		
12.		
13.		
14.		
15.		

Result:

Oh

* PASS = < 2,000 dpm

up

[Signature]



Last

RADIATION SURVEY FOR THE MONTH OF JULY, 2011

At Nuclear Medicine Facilities 2nd Floor.

INSTRUMENT USED: SURVEY METER (A)

SURVEY METER (B)



EXPANDED VIEW OF HOT LAB

mR/hr at location

	1	2	3	4	5	6	7	8	9	10	11	12	INITIALS
TRIGGER	0.05	0.05	0.05	0.08	0.15	0.05	0.08	0.08					
DATE													
7/19/2011	0.03	0.02	0.02	0.03	0.01	0.02	0.03	0.02					yrc

Se realizó survey en todo el departamento lecturas \leq a Bkg

This is to acknowledge the receipt of your letter application dated

8/31/2011, and to inform you that the initial processing which includes an administrative review has been performed.

- Amendment (52-15139-01) There were no administrative omissions. Your application was assigned to a technical reviewer. Please note that the technical review may identify additional omissions or require additional information.

- Please provide to this office within 30 days of your receipt of this card
-

A copy of your action has been forwarded to our License Fee & Accounts Receivable Branch, who will contact you separately if there is a fee issue involved.

Your action has been assigned **Mail Control Number** 575965.
When calling to inquire about this action, please refer to this control number.
You may call us on (610) 337-5398, or 337-5260.