

Catts, Michelle

From: Dries, Michael
Sent: Friday, September 10, 2010 5:48 PM
To: Catts, Michelle
Subject: FW: RCP Motors With Truncated Flow Chamber Modification

Michelle,

As a follow up to Rich Burroni's e-mail and my previous e-mail to you, Westinghouse confirmed below our present records and cleared up the mystery about two of the motors. Therefore a total of seven of the eight operating pumps have had the flow chamber modification and the listing is below. Only the motor on RCP-24 and our two spare motors have not been modified.

Mike

From: Dries, Michael
Sent: Friday, September 10, 2010 4:31 PM
To: Burroni, Richard J
Cc: Raffaele, Joseph J; Chan, Tat; Hixson, Matthew T
Subject: FW: RCP Motors With Truncated Flow Chamber Modification

Rich,

From my records:

LM-92P152	8/1999	RCP-34
2S-74P500	4/2001	RCP-32
1S-76P888	11/2002	RCP-22
3S-76P888	1/2006	RCP-33
1S-D001	12/2006	RCP-23
2S-76P888	11/2007	RCP-31
3S-74P500	3/2010	RCP-21

Mike

Information in this record was deleted
in accordance with the Freedom of Information
Act, exemptions
FOIA- ~~_____~~

From: Hixson, Matthew T [mailto:hixsonmt@westinghouse.com]
Sent: Friday, September 10, 2010 10:29 AM
To: Dries, Michael
Cc: Brady, David R.; Harms, Steve R
Subject: FW: RCP Motors With Truncated Flow Chamber Modification

The NRC was looking for this.

Could you lend some clarity on unit 2 v unit 3

From: Brady, David R.
Sent: Friday, September 10, 2010 9:47 AM
To: Harms, Steve R
Cc: Hixson, Matthew T; Stickel, Mark M.; Moxie, Jai

b-10

Subject: RCP Motors With Truncated Flow Chamber Modification

Steve,

Per your request, the following RCP motors at Indian Point have had the truncated flow chamber modification:

LM-92P152	8/1999
2S-74P500	4/2001
1S-76P888	11/2002
3S-76P888	1/2006
1S-D001	12/2006
2S-76P888	11/2007
3S-74P500	3/2010

Please note Indian Point swaps motors between units, thus I do not know present location of motors with respect to the unit it is installed in. The original shop order for unit #2 is 74P500 and unit #3 is 76P888. If you have further questions please let me know.

regards,

dave

David R. Brady
Principal Engineer
Rotating Equipment Services

Westinghouse Electric Company
Waltz Mill Facility
Madison, PA 15663, USA
Phone: +1 (724) 722-5639
Fax: +1 (724) 722-5424
Cell: (b)(6)
Email: bradydr@westinghouse.com
Home Page: www.westinghousenuclear.com

ex 6

~~EXEMPTED TO~~