



September 13, 2011

Traci Hollingshead
thollingshead@medx-ray.com

Dear Ms. Hollingshead:

You requested confirmation of return receipt and leak test records for radioactive devices shipped to:

Sioux Valley Hospital (Novoste Customer 20001785, USNRC License Number 40-12378-01)
1100 S. Euclid
Sioux Falls, SD 57117

Description of Devices Shipped to 20001785, Sioux Valley Hospital	Date Received back at Novoste	Serial
5F 60MM ACTIVE DEVICE	10/16/2003	81686
5F 40MM ACTIVE DEVICE	6/10/2003	84392
5F 60MM ACTIVE DEVICE	3/6/2003	85583
5F 60MM ACTIVE DEVICE	10/16/2003	86206
5F 30MM ACTIVE DEVICE	6/10/2003	86314
3.5F 40MM ACTIVE DEVICE	10/16/2003	89083
3.5F 40MM ACTIVE DEVICE	2/17/2005	90074
3.5F 40MM ACTIVE DEVICE	3/11/2004	90668
3.5F 60MM ACTIVE DEVICE	2/17/2005	91290
3.5F 40MM ACTIVE DEVICE	4/12/2005	91768

Novoste Corporation records available to Best Vascular, Inc. indicate that *all* of the radioactive devices that were shipped to the site were *all* received back from the site. Note: The retention period for leak test records has long since passed. For completeness, Best Vascular, Inc. *has not* transferred any radioactive devices to this site.

Kind regards

Craig Reed, RSO

4350 International Blvd., Norcross, GA 30093 USA
phone 770 717 0904 800 NOVOSTE (668 6783) fax 770 717 1283 877 753 8537
www.novoste.com www.bestvascular.com

AFRICA | ASIA | EUROPE | LATIN AMERICA | MIDDLE EAST | NORTH AMERICA



healthcare for everyone

Shipped to Sioux Valley Hospital
Received at Novoste

Catalog	Item Number	Description	Date	Order	Call	Serial	Qty
TDA-0030	520290-032	5F 30MM ACTIVE DEVICE	9/23/2002	S43776		86314	-1 Shipped
TDA-0030	520290-032	5F 30MM ACTIVE DEVICE	6/10/2003	R10021		86314	1 Received
TDA-0060	520290-060	5F 60MM ACTIVE DEVICE	1/3/2003	R10021		85583	-1 Shipped
TDA-0060	520290-060	5F 60MM ACTIVE DEVICE	3/6/2003	R11209		85583	1 Received
TDA-1040	P00552	3.5F 40MM ACTIVE DEVICE	1/22/2003	R10681		89083	-1 Shipped
TDA-1040	P00552	3.5F 40MM ACTIVE DEVICE	10/16/2003	CA4140	CA4140	89083	1 Received
TDA-0060	520290-060	5F 60MM ACTIVE DEVICE	2/5/2003	R11209		81686	-1 Shipped
TDA-0060	520290-060	5F 60MM ACTIVE DEVICE	10/16/2003	CA4502	CA4502	81686	1 Received
TDA-0040	520290-042	5F 40MM ACTIVE DEVICE	6/10/2003	R11446	CA1906	84392	1 Received
TDA-0040	520290-042	5F 40MM ACTIVE DEVICE				84392	-1 Shipped
TDA-1040	P00552	3.5F 40MM ACTIVE DEVICE	7/10/2003	R14863		90668	-1 Shipped
TDA-1040	P00552	3.5F 40MM ACTIVE DEVICE	3/11/2004	CA6199	CA6199	90668	1 Received
TDA-0060	520290-060	5F 60MM ACTIVE DEVICE	8/1/2003	R15239		86206	-1 Shipped
TDA-0060	520290-060	5F 60MM ACTIVE DEVICE	10/16/2003	CA6454	CA6454	86206	1 Received
TDA-1060	P00553	3.5F 60MM ACTIVE DEVICE	9/29/2003	R16310		91290	-1 Shipped
TDA-1060	P00553	3.5F 60MM ACTIVE DEVICE	2/17/2005	CA7145	CA7145	91290	1 Received
TDA-1040	P00552	3.5F 40MM ACTIVE DEVICE	1/9/2004	R17364		90074	-1 Shipped
TDA-1040	P00552	3.5F 40MM ACTIVE DEVICE	2/17/2005	CA7961	CA7961	90074	1 Received
TDA-1040	P00552	3.5F 40MM ACTIVE DEVICE	7/29/2004	R18809		91768	-1 Shipped
TDA-1040	P00552	3.5F 40MM ACTIVE DEVICE	4/12/2005	CA9208	CA9208	91768	1 Received