

JON RUNYAN
3RD DISTRICT, NEW JERSEY



COMMITTEE ON ARMED SERVICES
SUBCOMMITTEE ON
TACTICAL AIR AND LAND FORCES
SUBCOMMITTEE ON READINESS

COMMITTEE ON VETERANS' AFFAIRS
CHAIRMAN
SUBCOMMITTEE ON DISABILITY ASSISTANCE
AND MEMORIAL AFFAIRS
SUBCOMMITTEE ON HEALTH

Congress of the United States
House of Representatives
Washington, DC 20515-3003

COMMITTEE ON NATURAL RESOURCES
SUBCOMMITTEE ON FISHERIES, WILDLIFE,
OCEANS AND INSULAR AFFAIRS
RECEIVED
SEP 20 AM 9:09
FILES IN DIRECTIVES

September 13, 2011

Ms. Cindy Bladey
Chief, Rules, Announcements, and Directives Branch (RADB)
U.S. Nuclear Regulatory Commission
Mail Stop TWB-05-B01M
Washington, DC 20555-0001

7/18/2011
76 FR 42074
8

Dear Ms. Bladey,

I write today to post an official public comment regarding the Nuclear Regulatory Commission's (NRC) consideration of rulemaking to address prompt remediation of residual radioactivity during operations (Federal Register/Vol 76, No. 137/ June 17, 2011). I believe that a rule to require prompt remediation of radioactive contamination is necessary and should be implemented.

This proposed rule would have particular significance to many of my constituents, because the Oyster Creek Nuclear Generating Station lies within my district. This plant is scheduled to be decommissioned in 2019, and has a history of tritium leaks, including leaks that have reached the water table. I strongly encourage the NRC to pay close attention to contaminated water table remediation. If the water table becomes contaminated thousands of people can be at risk. This must be addressed.

I would also like to remind the NRC that radioactive leaks from corroded underground piping remain a serious concern. While prompt remediation would address the leaks, it would not address the root problem of corroded underground piping. It is likely that leaks will get worse as our infrastructure ages.

Thank you for the opportunity to provide comment.

Sincerely,

Jon Runyan
Member of Congress

JR/jb

SONSI Review Complete

MT. LAUREL
4167 CHURCH ROAD
MT. LAUREL, NJ 08054
(856) 780-6436
(856) 780-6439 (FAX)

WASHINGTON, D.C.
1239 LONGWORTH HOUSE OFFICE BUILDING
WASHINGTON, D.C. 20515
(202) 225-4765
(202) 225-0778 (FAX)
Runyan.House.Gov

ERIDS=ADM-03

TOMS RIVER
600 MULE ROAD
TOMS RIVER, NJ 08757
(732) 279-6013
(732) 279-6062 (FAX)

*Call =
C. Glenn (2591)*

Template=ADM-013