



Tennessee Valley Authority, Post Office Box 2000, Soddy Daisy, Tennessee 37384-2000

September 30, 2011

10 CFR 50.4

ATTN: Document Control Desk  
U.S. Nuclear Regulatory Commission  
Washington, D.C. 20555-0001

Sequoyah Nuclear Plant, Unit 1  
Facility Operating License No. DPR-77  
NRC Docket Nos. 50-327

**Subject: Revised Submittal Schedule for Supplemental Report for License Event Report 327/2011-003, "Unit 1 Reactor Trip As a Result of Turbine Control Card Failure"**

**Reference:** Letter from TVA to NRC, License Event Report 327/2011-003, "Unit 1 Reactor Trip As a Result of Turbine Control Card Failure," dated August 24, 2011

The purpose of this letter is to notify the NRC of a change in the submittal schedule for the supplemental report for License Event Report 327/2011-003. The reference letter provided the licensee event report and an expected supplemental report submittal date of September 30, 2011.

The root cause of the event is still being evaluated. Due to the need for additional evaluation and reviews, the expected submittal date of the supplemental report is changed to November 15, 2011.

There are no regulatory commitments contained in this letter. Should you have any questions concerning this submittal, please contact G. M. Cook, Sequoyah Site Licensing Manager, at (423) 843-7170.

Respectfully,

John T. Earlin  
Site Vice President  
Sequoyah Nuclear Plant

cc: NRC Regional Administrator – Region II  
NRC Senior Resident Inspector Sequoyah Nuclear Plant

IE22  
NRA