McCALLUM TESTING LABORATORIES, INC.

Geotechnical Engineering, Materials Testing & Environmental Services

September 15, 2011 REVISED October 6, 2011

Br. 3

U.S. Nuclear Regulatory Commission
Division of Nuclear Materials Safety - Region 1
475 Allendale Road
King of Prussia, PA 19406

Attention:

Sattar Lodhi

Subject:

Change of Radiation Safety Officer

03008912

U.S. Nuclear Regulatory Commission Materials License #45-15325-01

Dear Mr. Lodhi:

This letter is to inform you that as of September 16, 2011, Robert W. Mawyer has taken over the position of Radiation Safety Officer in place of Philip S. Berman on our U.S. Nuclear Regulatory Commission Materials License Number 45-15325-01.

Should you have any questions, please feel free to contact us at your earliest convenience.

Yours truly,

MCCALLUM TESTING DABORATORIES, INC.

John C. Pritchard

President

(email: karen@mccallumtesting.com)

cc: Robert W. Mawyer, RSO (email: rob@mccallumtesting.com)

NMSS/RGN1 MATERIALS-002

InstroTek, Inc. Radiation Safety Officer Training

Robert W. Mawyer

Has successfully completed a certified course on the responsibilities of Radiation Safety Officer for portable nuclear gauges using special form nuclear material.

Subjects included were:

Responsibilities of Radiation Safety Officer
Commercial shipping of portable nuclear gauges
Applicable 10 CFR Regulations
Portable nuclear gauge security
Records for tracking and logging portable gauges
Unit Conversions
Applying for nuclear materials license

InsiroTek.

InstroTek, Inc. 5908 Triangle Dr. Raleigh, NC 27617 (919) 875-8371 Radiation Safety Program
Applicable 49 CFR Regulations
NUREG 1556 Vol. 1 Rev. 1
Records for Dosimetry
Dose calculations and calculators
Decay calculations and calculators
Amending nuclear materials license

Instructor: Sean Reilly
Date of Training: 9/15/2011
Location: Concord, CA

There were no administrative of technical reviewer. Please not omissions or require additional	and to inform you that the initial processing which has been performed. (45-15325-01) omissions. Your application was assigned to a that the technical review may identify additional
	arwarded to our License Fee & Accounts Receivable arately if there is a fee issue involved.
Your action has been assigned Mail Control Number 576148. When calling to inquire about this action, please refer to this control number. You may call us on (610) 337-5398, or 337-5260.	
NRC FORM 532 (RI) (6-96)	Sincerely, Licensing Assistance Team Leader