

1320011

50-263

NRC DISTRIBUTION FOR PART 50 DOCKET MATERIAL

FILE NUMBER

INCIDENT REPORT

TO: Mr. J. G. Keppler

FROM: Northern States Pwr. Company  
Minneapolis, Minnesota  
L. O. Mayer

DATE OF DOCUMENT

7/11/77

DATE RECEIVED

7/18/77

LETTER  
 ORIGINAL  
 COPY

NOTORIZED  
 UNCLASSIFIED

PROP

INPUT FORM

NUMBER OF COPIES RECEIVED

100

DESCRIPTION

**DO NOT REMOVE**

**ACKNOWLEDGED**

PLANT NAME:

Monticello

(1-P)

RJL 7/18/77

ENCLOSURE

Licensee Event Report (RO 50-263/77-14) on 6/27/77 concerning air ejector radiation monitors being found inoperable following a startup after an outage.....

NOTE: IF PERSONNEL EXPOSURE IS INVOLVED SEND DIRECTLY TO KREGER/J. COLLINS

1 CY ENCL Rec'd

FOR ACTION/INFORMATION

BRANCH CHIEF:  
W/ 3 CYS FOR ACTION  
LIC ASST.:

Davis  
Diggs

INTERNAL DISTRIBUTION

REG FILE  
NRC-PDR  
I & E (2)  
MIPC  
SCHROEDER/IPPOLITO  
HOUSTON  
NOVAK/CHECK  
GRIMES  
KNIGHT  
BUTLER  
HANAUER  
TEDESCO  
EISENHIT  
BAER  
SHAO  
VOLLMER/BUNCH  
KREGER/ J. COLLINS  
ROSA

EXTERNAL DISTRIBUTION

L.PDR: **MINNEAPOLIS, MN.**  
TIC:  
NSIC:  
ACRS (16) SENT AS CAT. B

CONTROL NUMBER

771990261

D. Lanham IE

# NSP


NORTHERN STATES POWER COMPANY

MINNEAPOLIS, MINNESOTA 55401

July 11, 1977

Regulatory

File 974



Mr. J G Keppler, Director, Region III  
 Office of Inspection & Enforcement  
 U S Nuclear Regulatory Commission  
 799 Roosevelt Road  
 Glen Ellyn, IL 60137

Dear Mr Keppler:

MONTICELLO NUCLEAR GENERATING PLANT  
 Docket No. 50-263 License No. DPR-22

Air Ejector Radiation Monitors Found Inoperable  
 Following a Startup After an Outage

The Licensee Event Report for this occurrence is reproduced on the back of this letter. Enclosed are three copies.

Yours very truly,

A handwritten signature in cursive, appearing to read "L O Mayer".

L O Mayer, PE  
 Manager of Nuclear Support Services

LOM/MHV/deh

cc: Director, IE, USNRC (30)  
 Director, MIPC, USNRC (3)  
 G Charnoff  
 MPCA  
 Attn: J W Ferman

JUL 14 1977

771990261

