

50-263

NRC DISTRIBUTION FOR PART 50 DOCKET MATERIAL

FILE NUMBER  
INCIDENT REPORT

TO: Mr. J.G. Keppler

FROM: NSP  
Minneapolis, Minn. 55401  
L.O. Mayer

DATE OF DOCUMENT

7/25/77

DATE RECEIVED

7-25-77

LETTER  
 ORIGINAL  
 COPY

NOTORIZED  
 UNCLASSIFIED

PROP

INPUT FORM

NUMBER OF COPIES RECEIVED

100

DESCRIPTION: Ltr trans the following: 1P

ENCLOSURE Licensee Event rept # 77-13 concerning failure of SGTS train A due to improper installation of isolation valve controls in compressed storage bldg..... 1P

(1 cy encl rec'd)

ACKNOWLEDGED

DO NOT REMOVE

NOTE: IF PERSONNEL EXPOSURE IS INVOLVED SEND DIRECTLY TO KREGER/J. COLLINS

PLANT NAME: Monticello

DHL 7-26-77

FOR ACTION/INFORMATION

BRANCH CHIEF:

W/3 CYS FOR ACTION

LIC. ASST.:

W/ CYS

ACRS 10 CYS ~~10~~/SENT AS CAT B

DAVIS (7)

INTERNAL DISTRIBUTION

REG FILE

NRC PDR

I & E (2)

MIPC

SCHROEDER/IPPOLITO

HOUSTON

NOVAK/CHECK

GRIMES

BUTLER

HANAUER

TEDESCO/MACCARY

EISENHUT

BAER

SHAO

VOLLMER/BUNGH

KREGER/J. COLLINS

EXTERNAL DISTRIBUTION

CONTROL NUMBER

LPDR: Minneapolis, MN

TIC:

NSIC:

AD 4

772070020

By

# NSP

NORTHERN STATES POWER COMPANY

MINNEAPOLIS, MINNESOTA 55401

July 22, 1977

Mr J G Keppler, Director, Region III  
Office of Inspection & Enforcement  
U S Nuclear Regulatory Commission  
799 Roosevelt Road  
Glen Ellyn, IL 60137

Dear Mr Keppler:

MONTICELLO NUCLEAR GENERATING PLANT  
Docket No. 263 License No. DPR-22

SBGTS "A" Train Low Flow

The Licensee Event Report for this occurrence is reproduced on the back of this letter. Enclosed are 3 copies.

Yours very truly,

*M H Bath / for*

L O Mayer, PE  
Manager of Nuclear Support Services

LOM/MHV/ak

cc ~~Director~~, IE, USNRC (30)  
Director, MIPC, USNRC (3)  
G Charnoff  
MPCA  
Attn: J W Ferman

Regulatory

File Cy

772070020

