

NRC DISTRIBUTION FOR PART 50 DOCKET MATERIAL

FILE NUMBER  
INCIDENT REPORT

TO: Mr. J. G. Keppler

FROM: NSP  
Minneapolis, Minn. 55401  
L. O. Mayer

DATE OF DOCUMENT  
11/09/77  
DATE RECEIVED  
11/25/77

LETTER  
 ORIGINAL  
 COPY

NOTORIZED  
 UNCLASSIFIED

PROP

INPUT FORM

NUMBER OF COPIES RECEIVED  
**100**

DESCRIPTION

1p

PLANT NAME: MONTICELLO  
jcm 11/25/77

ENCLOSURE

Licensee Event Report (RO 50-263/77-30) on 10/10/77 concerning, during shutdown cooling operation discovered leak from B RHR loop relief valve 2005 2" boss connection, revealing crack in RHR line at point of boss connection....

1p

NOTE: IF PERSONNEL EXPOSURE IS INVOLVED  
SEND DIRECTLY TO KREGER/J. COLLINS

FOR ACTION/INFORMATION

BRANCH CHIEF: <b>(4)</b>	<b>DAVIS</b>		
<del>W/ S CYS FOR ACTION</del>			
<del>LIC ASST.:</del>			

INTERNAL DISTRIBUTION

<b>REG FILE</b>			
NRC PDR			
I & E (2)			
MIPC			
SCHROEDER/IPPOLITO			
HOUSTON			
NOVAK/CHECK			
GRIMES			
KNIGHT			
BUTLER			
HANAUER			
TEDESCO			
EISENHIT			
BAER			
SHAO			
VOLLMEER/BUNCH			
KREGER/ J. COLLINS			
ROSA			
<b>L CROCKER</b>			

EXTERNAL DISTRIBUTION

CONTROL NUMBER

LPDR: <b>MINNEAPOLIS MN.</b>			
TIC:			
NSIC:			
ACRS (16) SENT AS CAT. B			

**ADU**  
773290221

**NSP**

*D. Lankam*  
REGULATORY DOCKET FILE COPY

**NORTHERN STATES POWER COMPANY**

MINNEAPOLIS, MINNESOTA 55401

November 9, 1977



Mr J G Keppler, Director, Region III  
Office of Inspection & Enforcement  
U S Nuclear Regulatory Commission  
799 Roosevelt Road  
Glen Ellyn, IL 60137

Dear Mr Keppler:

MONTICELLO NUCLEAR GENERATING PLANT  
Docket No. 50-263 License No. DPR-22

Crack in B Loop LPCI Relief Valve Line

The Licensee Event Report for this occurrence is reproduced on the back of this letter. Enclosed are three copies.

Yours very truly,

L O Mayer, PE  
Manager of Nuclear Support Services

LOM/MHV/deh

cc: Director, IE, USNRC (30)  
Director, MIPC, USNRC (3)  
G Charnoff  
MPCA  
Attn: J W Ferman

NOV 14 1977

over

773290221

