

REPORT OF ABNORMAL OCCURRENCE AND/OR INCIDENT
NRC DISTRIBUTION FOR PART 50 DOCKET MATERIAL
(TEMPORARY FORM)

CONTROL NO: 6250

FILE: INCIDENT REPORT FILE

FROM: Northern States Power Co. Minneapolis, Mn 55401 L O Mayer		DATE OF DOC 6-6-75	DATE REC'D 6-9-75	LTR XXX	TWX	RPT	OTHER
TO: Mr. A Giambusso		ORIG Nonsigned	CC	OTHER	SENT AEC PDR <u>XXXX</u> SENT LOCAL PDR <u>XXXX</u>		
CLASS	UNCLASS XXXXX	PROP INFO	INPUT	NO CYS REC'D 40	DOCKET NO: 50-263		

DESCRIPTION:
 Ltr trans the following:

ACKNOWLEDGED

 PLANT NAME: Monticello

ENCLOSURES:
 Licensee Event Report on 5-26-75,
 During surveillance test, "A" Core Spray In-
 jection Valve, MO 1751, closed but would not
 reopen on signal from the control room...

 40 copy encl. rec'd

FOR ACTION/INFORMATION wtm 6-9-75

BUTLER (L) W/ Copies	SCHWENCER (L) W/ Copies	ZIEMANN (L) W/ 3 Copies	REGAN (E) W/ Copies
CLARK (L) W/ Copies	STOLZ (L) W/ Copies	DICKER (E) W/ Copies	LEAR (L) W/ Copies
PARR (L) W/ Copies	VASSALLO (L) W/ Copies	KNIGHTON (E) W/ Copies	SPELS W/ Copies
KNIEL (L) W/ Copies	PURPLE (L) W/ Copies	YOUNGBLOOD (E) W/ Copies	

INTERNAL DISTRIBUTION

<u>REG FILE</u> - NRC PDR - OGC, ROOM P-506A GOSSICK/STAFF - CASE GIAMBUSSO BOYD MOORE (L) DEYOUNG (L) SKOVHOLT (L) GOLLER (L) (Ltr) P. COLLINS DENISE REG OPR - FILE & REGION (2) - T.R. WILSON (3) STEELE	TECH REVIEW - SCHROEDER MACCARY KNIGHT PAWLICKI SHAO ** STELLO ** HOUSTON ** NOVAK - ROSS - IPPOLITO TEDESCO LONG LAINAS BENAROYA - VOLLMER	DENTON - GRIMES - GAMMILL KASTNER BALLARD SPANGLER ENVIRO MULLER DICKER KNIGHTON YOUNGBLOOD REGAN PROJECT LDR HARLESS	LIC ASST - R. DIGGS (L) - H. GEARIN (L) E. GOULBOURNE (L) P. KREUTZER (E) J. LEE (L) M. MAIGRET (L) S. REED (E) M. SERVICE (L) S. SHEPPARD (L) M. SLATER (E) H. SMITH (L) S. TEETS (L) G. WILLIAMS (E) V. WILSON (L) R. INGRAM (L)	A/T IND. BRAITMAN SALTZMAN MELTZ PLANS MCDONALD CHAPMAN DUBE (Ltr) E. COUPE PETERSON HARTFIELD (2) - KLECKER EISENHUT WIGGINTON - F. WILLIAMS - HANAUER
---	--	--	---	--

EXTERNAL DISTRIBUTION

- | | | |
|--|--------------------------------|---|
| - 1 - LOCAL PDR <u>Minneapolis, Mn</u> | - NATIONAL LABS _____ | 1 - PDR-SAN/LA/NY |
| - 1 - TIC (ABERNATHY) (1)(2)(10) | 1 - W. PENNINGTON, Rm E-201 GT | 1 - BROOKHAVEN NAT LAB |
| - 1 - NSIC (BUCHANAN) | 1 - CONSULTANTS | 1 - G. ULRIKSON, ORNL |
| 1 - ASLB | NEWMARK/BLUME/AGBABIAN | 1 - AGMED (RUTH GUSSMAN)
Rm B-127 GT |
| 1 - Newton Anderson | | 1 - J. D. RUNKLES, Rm E-201
GT |
| - 5 - ACRS SENT TO LIC ASST (DIGGS) | | |
| ** SEND ONLY TEN DAY REPORTS | | |

NSP


Regulatory Docket File

NORTHERN STATES POWER COMPANY

MINNEAPOLIS, MINNESOTA 55401

June 6, 1975

Mr. A. Giambusso, Director
Division of Reactor Licensing
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555



Dear Mr. Giambusso:

MONTICELLO NUCLEAR GENERATING PLANT
Docket No. 50-263 License No. DPR-22

Licensee Event Report to the NRC
Inoperable Core Spray Injection Valve

The Licensee Event Report for this occurrence is reproduced on the back of this letter.

Yours very truly,

A handwritten signature in cursive that reads "L. O. Mayer".

L. O. Mayer, PE
Manager, Nuclear Support Services

cc: J. G. Keppler
G. Charnoff
Minnesota Pollution Control Agency
Attn: E. A. Pryzina



6350

LICENSEE EVENT REPORT

CONTROL BLOCK:

--	--	--	--	--	--

(PLEASE PRINT ALL REQUIRED INFORMATION)

LICENSEE NAME						LICENSE NUMBER						LICENSE TYPE				EVENT TYPE								
01	M	N	M	N	P	1	0	0	-	0	0	0	0	0	-	0	0	4	1	1	1	1	0	1
7	8	9				14	15											26					31	32
CONT		CATEGORY		REPORT TYPE	REPORT SOURCE	DOCKET NUMBER				EVENT DATE				REPORT DATE										
01	P	O	T	L	0	5	0	-	0	2	6	3	0	5	2	6	7	5	0	6	0	6	7	5
7	8	57	58	59	60	61							68	69				74	75					80

EVENT DESCRIPTION

02	During surveillance test, "A" Core Spray Injection Valve, MO 1751, closed but would																							80
03	not reopen on signal from the control room. The valve was opened by hand. Valve																							80
04	has operated properly during subsequent testing. The redundant Core Spray System																							80
05	was operable. No previous similar failures have been experienced. Investigations																							80
06	revealed no apparent cause (AO 263/75-09).																							80

SYSTEM CODE		CAUSE CODE		COMPONENT CODE				PRIME COMPONENT SUPPLIER		COMPONENT MANUFACTURER				VIOLATION		
07	C	S	F	V	A	L	V	O	P	A	L	2	0	0	N	
7	8	9	10	11	12					17	43	44			47	48

CAUSE DESCRIPTION

08	Since no apparent cause for this occurrence has been determined no corrective action																							80
09	has been initiated. Limitorque Model SMB, Size 2.																							80
10																								80

FACILITY STATUS		% POWER		OTHER STATUS				METHOD OF DISCOVERY		DISCOVERY DESCRIPTION				
11	F	0	8	0	NA				B	NA				
7	8	9	10	12	13				44	45	46			80
FORM OF ACTIVITY RELEASED		CONTENT OF RELEASE		AMOUNT OF ACTIVITY				LOCATION OF RELEASE						
12	Z	Z	NA											
7	8	9	10	11					44	45				80

PERSONNEL EXPOSURES

NUMBER		TYPE		DESCRIPTION	
13	0	0	0	Z	NA
7	8	9	11	12	13

PERSONNEL INJURIES

NUMBER		DESCRIPTION		
14	0	0	0	NA
7	8	9	11	12

Probable Consequences

15	NA																							80
----	----	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	----

LOSS OR DAMAGE TO FACILITY

TYPE		DESCRIPTION	
16	Z	NA	
7	8	9	10

PUBLICITY

17	NA																							80
----	----	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	----

ADDITIONAL FACTORS

18	NA																							80
----	----	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	----

19	NA																							80
----	----	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	----

NAME: O. N. Iverson PHONE: 612-295-5151