

MEMO ROUTE SLIP Form AEC-93 (Rev. May 14, 1947) AEC-M 0240		See me about this. Note and return.	For conference. For signature.	For action. For information.
TO (Name and unit) RO Chief, FS&EB RO:HQ (4) Licensing (4) <u>DR Central Files</u> Region I		INITIALS	REMARKS Northern States Power Company Monticello 50-263	
		DATE		
TO (Name and unit) Region II Local PDR PDR NSIC TIC		INITIALS	REMARKS	
		DATE		
TO (Name and unit) OGC, Beth 506A A. Roisman F. Rizzo, RO:HQ A/D for Info. Processing, OOE		INITIALS	REMARKS	
		DATE		
FROM (Name and unit) G. Fiorelli RO:III		REMARKS Attached a supplement dated 1-9-75 to licensee's reply dated 12-23-74, to RO Bulletin 74-10A.		
PHONE NO.	DATE 1-15-75			

USE OTHER SIDE FOR ADDITIONAL REMARKS

GPO : 1971 O - 445-469

2
ADK



NORTHERN STATES POWER COMPANY

MINNEAPOLIS, MINNESOTA 55401

January 9, 1975

Mr J G Keppler, Regional Director
Directorate of Regulatory Operations
Region III
United States Atomic Energy Commission
799 Roosevelt Road
Glen Ellyn, Illinois 60137

Dear Mr Keppler:

MONTICELLO NUCLEAR GENERATING PLANT
DOCKET 50-263 LICENSE DPR-22

Our December 23, 1974 response to DRO Bulletin 74-10A stated that we planned to reinspect the four welds of four inch line to bypass loop weldolets, and that we would consider reinspection of additional bypass line welds.

After learning of the recent findings on additional reinspections we now plan a 100% reinspection of all four inch bypass loop welds during the current refueling outage.

Yours very truly,

L J Wachter, Vice President
Power Production - System Operation

LJW/ma

cc: Mr E G Case
Mr G Charnoff
Mr E A Pryzina
Assistant Director for Construction
and Operations - AEC

JAN 15 1975