

FILE: _____

FROM: Northern States Power Company Monticello, Minn. 55362 Mr. C.E. Larson			DATE OF DOC 1-30-74	DATE REC'D 1-30-74	LTR	MEMO	RPT	OTHER facsimile
TO: Mr. J.G. Keppler			ORIG 1	CC	OTHER	SENT AEC PDR <u>XXX</u> SENT LOCAL PDR <u>XXX</u>		
CLASS	UNCLASS XXX	PROP INFO	INPUT	NO CYS REC'D 1		DOCKET NO: 50-263		

DESCRIPTION:
Ltr reporting an abnormal occurrence at the Monticello Nuclear Generating Plant concern a RCIC Steam Line High Area Temperature switch which was found to trip outside of tech specs & was replaced.....

PLANT NAME: Monticello

ENCLOSURES:

ACKNOWLEDGED

DO NOT REMOVE

FOR ACTION/INFORMATION 1-31-74 JB

- | | | | |
|------------------------|---------------------------|-----------------------------|-----------------------|
| BUTLER(L)
W/ Copies | SCHWENCER(L)
W/ Copies | ✓ ZIEMANN(L)
W/ 7 Copies | REGAN(E)
W/ Copies |
| CLARK(L)
W/ Copies | STOLZ(L)
W/ Copies | DICKER(E)
W/ Copies | W/ Copies |
| GOLLER(L)
W/ Copies | VASSALLO(L)
W/ Copies | KNIGHTON(E)
W/ Copies | W/ Copies |
| KNIEL(L)
W/ Copies | SCHEMEL(L)
W/ Copies | YOUNGBLOOD(E)
W/ Copies | W/ Copies |

INTERNAL DISTRIBUTION

- | | | | | |
|--------------------|--------------------|----------------|-----------------|----------------|
| ✓ <u>REG FILE</u> | <u>TECH REVIEW</u> | DENTON | <u>LIC ASST</u> | <u>A/T IND</u> |
| ✓ AEC PDR | ✓ HENDRIE | GRIMES | | BRAITMAN |
| ✓ OGC, ROOM P-506A | SCHROEDER | GAMMILL | ✓ DIGGS (L) | SALTZMAN |
| ✓ MUNTZING/STAFF | ✓ MACCARY | KASTNER | GEARIN (L) | B. HURT |
| ✓ CASE | ✓ KNIGHT | BALLARD | GOULBOURNE (L) | <u>PLANS</u> |
| GIAMBUSSO | ✓ PAWLICKI | SPANGLER | LEE (L) | MCDONALD |
| BOYD | ✓ SHAO | | MAIGRET (L) | DUBE w/Input |
| MOORE (L)(BWR) | ✓ STELLO | <u>ENVIRO</u> | SERVICE (L) | <u>INFO</u> |
| DEYOUNG(L)(PWR) | ✓ HOUSTON | MULLER | SHEPPARD (E) | C. MILES |
| ✓ SKOVHOLT (L) | ✓ NOVAK | DICKER | SMITH (L) | ✓ B. KING |
| P. COLLINS | ✓ ROSS | KNIGHTON | TEETS (L) | |
| DENISE | ✓ IPPOLITO | YOUNGBLOOD | WADE (E) | |
| ✓ REG OPR | ✓ TEDESCO | REGAN | WILLIAMS (E) | |
| FILE & REGION(3) | ✓ LONG | PROJECT LDR | WILSON (L) | |
| ✓ MORRIS | ✓ LAINAS | | | |
| ✓ STEELE | ✓ BENAROYA | <u>HARLESS</u> | | |
| | ✓ VOLLMER | | | |

EXTERNAL DISTRIBUTION

- | | | |
|---|------------------------------|------------------------|
| ✓ 1 - LOCAL PDR <u>Minneapolis, Minn.</u> | (1)(2)(10)-NATIONAL LAB'S | 1-PDR-SAN/LA/NY |
| ✓ 1 - DTIE(ABERNATHY) | 1-ASLBP(E/W Bldg, Rm 529) | 1-GERALD LELLOUCHE |
| ✓ 1 - NSIC(BUCHANAN) | 1-W. PENNINGTON, Rm E-201 GT | BROOKHAVEN NAT. LAB |
| 1 - ASLB(YORE/SAYRE/
WOODARD/"H" ST. | 1-CONSULTANT'S | 1-AGMED(Ruth Gussman) |
| ✓ 16 - CYS ACRS XXXXXX Sent to Diggs | NEWMARK/BLUME/AGBABIAN | RM-B-127, GT. |
| 1-31-74 | 1-GERALD ULRIKSON...ORNL | 1-RD..MULLER..F-309 GT |

Rg


Record 1/30
5.00



NORTHERN STATES POWER COMPANY
Monticello, Minnesota 55362

January 30, 1974

Mr. J. G. Keppler, Regional Director
Directorate of Regulatory Operations
Region III
United States Atomic Energy Commission
799 Roosevelt Road
Glen Ellyn, Illinois 61037



Dear Mr. Keppler:

MONTICELLO NUCLEAR GENERATING PLANT
Docket No. 50-263 License No. DPR-22

On January 29, 1974, while performing a quarterly surveillance test, one of sixteen RCIC Steam Line High Area Temperature switches was found to trip outside of Technical Specification limits. In accordance with Section 3.2.1 of the Technical Specifications, the RCIC Steam Line High Area Temperature Switches must be set at $\leq 200^{\circ}\text{F}$. The temperature switch was initially found to trip at 205°F . The switch tripped within specified limits upon subsequent retests; however, the switch is considered defective and has been replaced.


Yours very truly,

C E Larson

C. E. Larson
Plant Manager Monticello

CEL/kik

cc: J F O'Leary
G Charnoff
Minnesota Pollution Control Agency
Attn: E. A. Pryzina
File



Copies sent by Telecopier to Keppler and O'Leary

835

55