

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:8007100195 DOC,DATE: 80/07/01 NOTARIZED: NO DOCKET #
 FACIL:50-263 Monticello Nuclear Generating Plant, Northern States 05000263
 AUTH.NAME AUTHOR AFFILIATION
 JACOBSON,R.D. Northern States Power Co.
 RECIP.NAME RECIPIENT AFFILIATION
 Region 3, Chicago, Office of the Director

SUBJECT: LER 80-023/03L-0:on 800601,air ejector off gas radiation monitors dropped to about 20% normal for about 40 minutes. Caused by mechanical vacuum pump off gas sample valve being incorrectly opened,Valve now wired shut.

DISTRIBUTION CODE: A002S COPIES RECEIVED:LTR 1 ENCL 1 SIZE: 1+1
 TITLE: Incident Reports

NOTES: _____

ACTION:	RECIPIENT	COPIES		RECIPIENT	COPIES	
	ID CODE/NAME	LTR	ENCL	ID CODE/NAME	LTR	ENCL
	BC <u>IPPOLITO,T.05</u>	1	1	PM <u>KEVERN,T. 06</u>	2	2
INTERNAL:	A/D COMP&STRUCT	1	1	A/D CORE & CS	1	1
	A/D ENV TECH	1	1	A/D GEN PROJ	1	1
	A/D LICENSING	1	1	A/D MATL & QUAL	1	1
	A/D OP REACTORS	1	1	A/D PLANT SYS	1	1
	A/D RAD PROT	1	1	A/D SFTY ASSESS	1	1
	A/D TECHNOLOGY	1	1	ACC EVAL BR	1	1
	AEOD	10	10	AUX SYS BR	1	1
	CHEM ENG BR	1	1	CONT SYS BR	1	1
	CORE PERF BR	1	1	DIR,ENGINEERING	1	1
	DIR,HUM FAC SFY	1	1	DIR,SFTY TECH	1	1
	DIR,SYS INTEG	1	1	EFF TR SYS BR	1	1
	EMERG PREP	1	1	ENV ENG BR	1	1
	EQUIP QUAL BR	1	1	GEN ISSUES BR	1	1
	GEOSCIENCES	1	1	HUM FACT ENG BR	1	1
	HYD/GEO BR	1	1	I&C SYS BR	1	1
	I&E 09	2	2	JORDAN,E./IE	1	1
	LIC GUID BR	1	1	LIC QUAL BR	1	1
	MATL ENG BR	1	1	MECH ENG BR	1	1
	MOORE,V.	1	1	MPA 11	3	3
	NRC PDR 02	1	1	OP EX EVAL BR	3	3
	OR ASSESS BR	1	1	POWER SYS BR	1	1
	PPAS	1	1	PROC/TST REV BR	1	1
	QA BR	1	1	RAD ASSESS BR	1	1
	REACT SYS BR	1	1	<u>REG FILE</u> 01	1	1
	REL & RISK A BR	1	1	SFTY PROG EVAL	1	1
	SIT ANAL BR	1	1	STRUCT ENG BR	1	1
	SYS INTERAC BR	1	1	TERA:DOUG MAY	1	1
EXTERNAL:	ACRS	16	16	LPDR 03	1	1
	NSIC 04	1	1			

JUL 11 1980

NSP

NORTHERN STATES POWER COMPANY

MINNEAPOLIS, MINNESOTA 55401

July 1, 1980

Mr J G Keppler
Office of Inspection & Enforcement
U S Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, IL 60137

Dear Mr Keppler:

MONTICELLO NUCLEAR GENERATING PLANT
Docket No. 50-263 License No. DPR-22

Low Reading on Air Ejector Process Radiation Monitors

The Licensee Event Report for this occurrence is reproduced on the back of this letter. Enclosed are three copies.

This event is reported in compliance with Technical Specification 6.7.B.2.b. in that it represents operation in a degraded mode for a short period of time as allowed by the Limiting Conditions for Operation.

Yours very truly,

David Musolf 7/1/80

L O Mayer, PE
Manager of Nuclear Support Services

LOM/DMM/jh

cc: ~~Director~~, IE, USNRC (30)
Director, MIPC, USNRC (3)
MPCA
Attn: J W Ferman

*A02
S.11*

-over-

10
8007 0190

S

