Central file



145 MARTINVALE LANE • SAN JOSE, CALIFORNIA 95119 • PHONE (408) 629-9800 • TELEX 352062

ADDISON B. HIGGINBOTHAM, P.E.

Manager — Mechanical Systems Engineering

August 31, 1979 ABH-79-028 NSP-37-018

D 265

Mr. James G. Keppler, Director Region III Office of Inspection and Enforcement U.S. Nuclear Regulatory Commission 799 Roosevelt Road Glen Ellyn, Illinois 60137

Subject: IE Bulletin 79-14, Inspection Plan Revision

Monticello Nuclear Generating Plant

Dear Mr. Keppler:

Enclosed are two (2) copies of NUTECH Report NSP-37-005, Revision 1, titled "IE Bulletin 79-14, Safety Related Piping Systems, Inspection Plan, Monticello Nuclear Generating Plant." The revised document incorporates the requirements of the supplement to IE Bulletin 79-14 that was issued August 15, 1979, and modifies the inspection phase for several segments of piping. The document is being transmitted to you at the request of Northern States Power Company.

Sincerely yours,

A. B. Higginbotham, P/E. Engineering Manager

ABH:ce

Enclosures

cc: L. R. Eliason w/o Enclosures

R. A. Goranson w/o Enclosures

L. O. Mayer w/o Enclosures

- FILE: 30.0237.0005

0,1979

**ડ**ર્