

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8605120424 DOC. DATE: 86/05/05 NOTARIZED: NO DOCKET #
 FACIL: 50-263 Monticello Nuclear Generating Plant, Northern States 05000263
 AUTH. NAME AUTHOR AFFILIATION
 MUSOLF, D. Northern States Power Co.
 RECIP. NAME RECIPIENT AFFILIATION
 DENTON, H. R. Office of Nuclear Reactor Regulation, Director (post 851125)

SUBJECT: Forwards application for amend to License DPR-22, changing
 Tech Specs to eliminate interpretation problems encountered
 during 1984 refueling & recirculation piping replacement
 outage. Fee paid.

DISTRIBUTION CODE: A001D COPIES RECEIVED: LTR 3 ENCL 40 SIZE: 2444
 TITLE: OR Submittal: General Distribution

NOTES:

RECIPIENT		COPIES		RECIPIENT		COPIES	
ID	CODE/NAME	LTTR	ENCL	ID	CODE/NAME	LTTR	ENCL
BWR	ADTS	1	0	BWR	EB	1	1
BWR	EICSB	2	2	BWR	FOB	1	1
BWR	PD1 PD 01	5	5	AULUCK, R		1	1
BWR	PSB	1	1	BWR	RSB	1	1
INTERNAL:	ADM/LFMB	1	0	ELD/HDS1		1	0
	NRR/DHFT/TSCB	1	1	NRR/ORAS		1	0
	<u>REG FILE</u> 04	1	1	RGN3		1	1
EXTERNAL:	24X	1	1	EG&G BRUSKE, S		1	1
	LPDR 03	1	1	NRC PDR 02		1	1
	NSIC 05	1	1				

w/check

\$150.00

#124444



Northern States Power Company

414 Nicollet Mall
Minneapolis, Minnesota 55401
Telephone (612) 330-5500

May 5, 1986

Harold R Denton, Director
Office of Nuclear Reactor Regulation
U S Nuclear Regulatory Commission
Washington, DC 20555

MONTICELLO NUCLEAR GENERATING PLANT
Docket No. 50-263 License No. DPR-22

License Amendment Request Dated May 5, 1986
Miscellaneous Technical Specification Improvements

Attached are three originals and 37 conformed copies of a request for a change in the Technical Specifications, Appendix A of the Operating License, for the Monticello Nuclear Generating Plant. This request is submitted in accordance with the provisions of 10 CFR Part 50, Section 50.90. A check is attached in the amount of \$150.00 in accordance with the requirements of 10 CFR Part 170 for the amendment application fee.

The proposed changes are a result of a detailed review of the Monticello Technical Specifications that occurred following the 1984 refueling and recirculation piping replacement outage. The outage was nearly a year in length and a number of unusual system configurations were encountered. As a result, several Technical Specification interpretation problems arose which were resolved on a case by case basis with NRC Region III and the Office of Nuclear Reactor Regulation. The purpose of this submittal is to satisfy our commitment to submit necessary proposed changes to the Technical Specifications to eliminate future interpretation problems.


Exhibit A contains a description of the proposed changes, the reasons for requesting the changes, and a Significant Hazards Determination. Exhibit B contains pages of the Monticello Technical Specifications revised to show the proposed changes.

8605120424 860505
PDR ADDCK 05000263
P PDR

Accol
3/40
w/checked
\$150.00
#124444

Director of NRR
May 5, 1986
Page 2

Please contact us if you have any questions related to this request or if additional information is required to supplement it.



David Musolf
Manager - Nuclear Support Services

c: Regional Administrator III, NRC
Resident Inspector, NRC
NRR Project Manager, NRC
G Charnoff
Minnesota Pollution Control Agency (State Contact)
Attn: Dr J W Ferman

Attachments