

# REGULATOR INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8608050207 DOC. DATE: 86/07/30 NOTARIZED: NO DOCKET #  
 FACIL: 50-263 Monticello Nuclear Generating Plant, Northern States 05000263  
 AUTH. NAME AUTHOR AFFILIATION  
 MUSOLF, D. Northern States Power Co.  
 RECIP. NAME RECIPIENT AFFILIATION  
 Office of Nuclear Reactor Regulation, Director (post 851125)

SUBJECT: Forwards 39 new binders for three addl updated SAR vols &  
 13 sets of new updated SAR cover inserts to replace existing  
 covers for Rev 4 to updated SAR submitted to NRC by  
 860630 ltr.

DISTRIBUTION CODE: A053D COPIES RECEIVED: LTR 1 ENCL 13 SIZE: 1  
 TITLE: OR Submittal: Updated FSAR (50.71)

## NOTES:

RECIPIENT		COPIES		RECIPIENT		COPIES	
ID CODE/NAME		LTTR	ENCL	ID CODE/NAME		LTTR	ENCL
BWR ADTS		1	0	BWR EB		1	0
BWR EICSB		2	0	BWR FOB		1	0
BWR PD1 LA		1	0	BWR PD1 PD		1	0
AULUCK, R	01	1	1	BWR PSB		1	0
BWR RSB		1	0				
INTERNAL: IE FILE	05	1	1	NRR ROE, M. L		1	1
<u>REG FILE</u>	02	1	1	RGN3	06	2	2
EXTERNAL: DMB/DSS		1	1	FRANKLIN		1	1
LPDR	04	1	1	NRC PDR	03	1	1
NSIC		1	1				

*Sets of Binders*

TOTAL NUMBER OF COPIES REQUIRED: LTTR 20 ENCL 11



Northern States Power Company

414 Nicollet Mall  
Minneapolis, Minnesota 55401  
Telephone (612) 330-5500

July 30, 1986

Director  
Office of Nuclear Reactor Regulation  
U S Nuclear Regulatory Commission  
Washington, DC 20555

MONTICELLO NUCLEAR GENERATING PLANT  
Docket No. 50-262 License No. DPR-22

Binders and Covers for Recent Monticello Updated  
Safety Analysis Report Revision

Revision 4 to the Monticello Updated Safety Analysis Report was submitted to the NRC by letter dated June 30, 1986. This revision of the USAR included three new volumes and new cover inserts for the USAR binders. However, through an oversight, the binders for the three new volumes and the new cover inserts for all seven USAR binders were not supplied with the 13 copies of revision 4 sent to the NRC. Accompanying this letter you will find thirty-nine new binders for the three additional USAR volumes, and thirteen sets of new USAR cover inserts to replace the existing covers.

We apologize for any inconvenience this oversight may have created. If you have any questions about the material supplied, please contact us.

David Musolf  
Manager - Nuclear Support Services

DMM/MMV/mmv

c: NRR Project Manager, NRC  
Resident Inspector, NRC  
G Charnoff

8608050207 860730  
PDR ADDCK 05000263  
K PDR

*A053  
1/13 Sets  
of Binders*