REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:8001100513 DOC.DATE: 79/12/31 NOTARIZED: NO DOCKET # FACIL: 50-263 Monticello Nuclear Generating Plant, Northern States AUTH, NAME AUTHOR AFFILIATION

05000263

MAYER, L.O. RECIP NAME

Northern States Power Co. RECIPIENT AFFILIATION

Office of Nuclear Reactor Regulation

SUBJECT: Forwards Factory Mutual Engineering Corp 670223 rept, "Pyralarm Detectors F3/5A & F5B (Sensitivity to Polyviny/ Chlorine Combustion), in response to NRC 790829 fire protection safety evaluation Sections 3,3,1(a) & 4,2,

/ ENCL DISTRIBUTION CODE: A006S COPIES RECEIVED:LTR TITLE: Fire Protection Information (After Issuance of OP.

ACTION:	RECIPIENT 10 CODEZNAME 05 BC ORB #3	COPIES LITE ENG		COPIES LTTR ENCL
INTERNAL:	01 FG FILE 09 I&E 12 AUXIL SYS BR 19 WAMBACH OELD	1 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	2 14 PLANT SYS BR 20 MURANAKA,R	1 1 1 1 5 5 1 1
EXTERNAL:	03 LPDR 22 ACRS	1 16 16	04 NSIC	1 1

CAM I Judy

NSP

NORTHERN STATES POWER COMPANY

MINNEAPOLIS, MINNESOTA 55401

December 31, 1979

Director of Nuclear Reactor Regulation U S Nuclear Regulatory Commission Washington, DC

Monticello Nuclear Generating Plant Docket No. 50-263 License No. DPR-22

Fire Detector Sensitivity Evaluation
Required by the Fire Protection Safety Evaluation

Sections 3.2.1(a) and 4.2 of the Monticello Fire Protection Safety Evaluation report issued by the NRC Staff on August 29, 1979 requires the submittal of test reports concerning the adequacy of smoke detectors to detect products of combustion of materials located in the plant. The attached reports provide information related to the performance of our Pyrotronics detectors in sensing products of combustion from cable and miscellaneous other combustible material.

Please contact us if you have any questions related to the information we have provided.

L O Mayer, PE

Manager of Nuclear Support Services

Dais per, M Ciso Ci

LOM/DMM/ak

cc: J G Keppler

G Charnoff

Attachments

A03/

1.811