

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8603110221 DOC. DATE: 86/02/28 NOTARIZED: NO DOCKET #
 FACIL: 50-263 Monticello Nuclear Generating Plant, Northern States 05000263
 AUTH. NAME AUTHOR AFFILIATION
 MUSOLF, D. Northern States Power Co.
 RECIP. NAME RECIPIENT AFFILIATION
 Office of Nuclear Reactor Regulation, Director (post 851125)

SUBJECT: Advises that hold placed on infrequently used procedures, per 831104 commitment to rept results of check of vendor & engineering recommendations in test & maint procedures by 860301, in response to Generic Ltr 83-28, Item 3.2.

DISTRIBUTION CODE: A055D COPIES RECEIVED: LTR 1 ENCL 0 SIZE: 1
 TITLE: OR/Licensing Submittal: Salem ATWS Events GL-83-28

NOTES:

	RECIPIENT ID CODE/NAME	COPIES		RECIPIENT ID CODE/NAME	COPIES	
		LTR	ENCL		LTR	ENCL
	BWR ADTS	1	1	BWR PD1 PD 01	3	3
	BWR EB	1	1	BWR EICSB	1	1
	BWR FOB	1	1	AULUCK, R	1	1
	BWR PSB	1	1	BWR RSB	1	1
INTERNAL:	ADM/LFMB	1	0	ELD/HDS1	1	0
	IE/DI	1	1	IE/DGAVT	1	1
	NRR BWR ADTS	1	1	NRR LASHER, D	1	1
	NRR PWR-A ADTS	1	1	NRR PWR-B ADTS	1	1
	NRR/DSRO/RSIB	1	1	NRR/DRAS	1	1
	NRR/TAMB	1	1	<u>REG FILE</u> 04	1	1
	RGN3	1	1			
EXTERNAL:	24X	1	1	LPDR 03	1	1
	NRC PDR 02	1	1	NSIC 05	1	1

TOTAL NUMBER OF COPIES REQUIRED: LTR 27 ENCL 25



Northern States Power Company

414 Nicollet Mall
Minneapolis, Minnesota 55401
Telephone (612) 330-5500

February 28, 1986

Director
Office of Nuclear Reactor Regulation
US Nuclear Regulatory Commission
Washington, DC 20555

MONTICELLO NUCLEAR GENERATING PLANT
DOCKET NO. 50-263 LICENSE NO. DPR-22

Generic Letter 83-28, Salem Action Plan, Item 3.2
Check of Vendor and Engineering Recommendations


In our letter dated November 4, 1983 we provided our commitment to report the results of our check of vendor and engineering recommendations in test and maintenance procedures by March 1, 1986. The administrative process for completing this review was described in our letter dated December 30, 1983.

Procedures currently approved for use at the Monticello Nuclear Generating Plant have been reviewed to assure that appropriate vendor and engineering recommendations relating to test guidance have been incorporated. A hold has been placed on infrequently used procedures for which the required review has not been completed.

Please contact us if you have any questions related to the actions we have taken to address this Salem Action Plan requirement.

David Musolf
Manager Nuclear Support Services

c: NRR Project Manager, NRC
Resident Inspector, NRC
Regional Administrator, Region III, NRC
G Charnoff



A055
1/0