

From: Weidner, Tara
Sent: Thursday, October 27, 2011 3:02 PM
To: 'slong@nationalphysics.com'
Subject: H. James Stanton, M.D. renewal

License No. 47-25572-01
Docket No. 030-35785
Control No. 575180

SUBJECT: H. James Stanton, M.D. Renewal

Ms. Long,

As a follow-up to our conversation earlier today, here are the items that I will need to complete the review of the license renewal.

1. Please confirm that no PET isotopes are being used at this facility.
2. In Item 10.d. of the application dated May 16, 2011, the licensee stated that, "We have developed and will implement and maintain procedures for the safe responses to spills of licensed materials in accordance with 10 CFR 20.1101." Please confirm that the aforementioned procedures will be in a written form.
3. The provided facility diagram describes the principal activities of the areas adjacent to the radioactive material use areas, however, we also need a description of the areas above and below these areas of use.
4. The facility diagram appears to have changed from the diagram provided in the letter dated January 8, 2002 (e.g. the hot lab moved across the hall and a camera room and echo room have switched places. Please provide copies of the close-out surveys used to release these areas.

I will need this additional information no later than Monday, November 7, 2011. Earlier today you indicated that you would be able to provide a quick turnaround, I thank you for that. If you have any questions, call me at 610-337-5272.

Sincerely,

Tara L. Weidner

Health Physicist

US Nuclear Regulatory Commission