



**UNITED STATES
NUCLEAR REGULATORY COMMISSION**
REGION II
245 PEACHTREE CENTER AVENUE NE, SUITE 1200
ATLANTA, GEORGIA 30303-1257

November 1, 2011

Mr. David Precht
Manager, Columbia Plant
Westinghouse Electric Company
Commercial Nuclear Fuel Division
5801 Bluff Road, Drawer R
Columbia, SC 29250

SUBJECT: ERRATA WESTINGHOUSE ELECTRIC COMPANY- NRC INTEGRATED
INSPECTION REPORT NO. 070-1151/2011-004 AND NOTICE OF VIOLATION

Dear Mr. Precht:

On October 27, 2011, the United States Nuclear Regulatory Commission (NRC) issued the subject NRC Integrated Inspection Report 07001151/2011-004 for Westinghouse Electric Company, ADAMS ML11301A109. In reviewing this report it was noted that in Attachment Section 2, the notation for the closed items was incorrect. The correct notation is EEI 70-1151/2011-004-01 versus VIO 70-1151/2011-004-01 and LER 70-1151/2011-001-0 and URI 70-1151/2011-002-02 were switched with their descriptions. The correct notations have been made as stated above. Accordingly, we are providing a revised version of the inspection report that includes the notations.

Should you have any questions concerning this letter, please contact me at 404-997-4629.

Sincerely,

/RA by M. Thomas for/

Marvin D. Sykes, Chief
Fuel Facility Inspection Branch 3
Division of Fuel Facility Inspection

Docket No. 070-1151
License No. SNM-1107

Enclosure: As stated

cc w/encls: (See page 2)

November 1, 2011

Mr. David Precht
Manager, Columbia Plant
Westinghouse Electric Company
Commercial Nuclear Fuel Division
5801 Bluff Road, Drawer R
Columbia, SC 29250

SUBJECT: ERRATA WESTINGHOUSE ELECTRIC COMPANY- NRC INTEGRATED
INSPECTION REPORT NO. 070-1151/2011-004 AND NOTICE OF VIOLATION

Dear Mr. Precht:

On October 27, 2011, the United States Nuclear Regulatory Commission (NRC) issued the subject NRC Integrated Inspection Report 07001151/2011-004 for Westinghouse Electric Company, ADAMS ML11301A109. In reviewing this report it was noted that in Attachment Section 2, the notation for the closed items was incorrect. The correct notation is EEI 70-1151/2011-004-01 versus VIO 70-1151/2011-004-01 and LER 70-1151/2011-001-0 and URI 70-1151/2011-002-02 were switched with their descriptions. The correct notations have been made as stated above. Accordingly, we are providing a revised version of the inspection report that includes the notations.

Should you have any questions concerning this letter, please contact me at 404-997-4629.

Sincerely,

/RA by M. Thomas for/

Marvin D. Sykes, Chief
Fuel Facility Inspection Branch 3
Division of Fuel Facility Inspection

Docket No. 070-1151
License No. SNM-1107

Enclosure: As stated

cc w/encls: (See page 2)

☒ PUBLICLY AVAILABLE

☐ NON-PUBLICLY AVAILABLE

☐ SENSITIVE

☒ NON-SENSITIVE

ADAMS: ☒ Yes

ACCESSION NUMBER: ML113050532

☒ SUNSI REVIEW COMPLETE ☒ FORM 665 ATTACHED

OFFICE	RII:DFFI						
SIGNATURE	/RA/						
NAME	MThomas						
DATE	11/1/2011	11/ /2011	11/ /2011	11/ /2011	11/ /2011	11/ /2011	11/ /2011
E-MAIL COPY?	YES NO	YES NO	YES NO	YES NO	YES NO	YES NO	YES NO

OFFICIAL RECORD COPY DOCUMENT NAME: G:\DNMS\I\FBI\REPORTS\FINAL REPORTS\WEST\2011\ERRATA
WESTINGHOUSE 2011-004.DOCX

cc w/encl(s):

Marc Rosser

Manager

Environment, Health and Safety

Commercial Nuclear Fuel Division

Electronic Mail Distribution

Susan E. Jenkins

Assistant Director, Division of Waste Management

Bureau of Land and Waste Management

Department of Health and Environmental Control

Electronic Mail Distribution

Letter to Mr. David Precht from Marvin D. Sykes dated November 1, 2011

Subject: ERRATA WESTINGHOUSE ELECTRIC COMPANY- NRC INTEGRATED
INSPECTION REPORT NO. 070-1151/2011-004 AND NOTICE OF VIOLATION

Distribution w/encl(s):

M. Thomas, RII
O. López, RII
C. Ryder, NMSS
M. Baker, NMSS
M. Sykes, RII

ATTACHMENT

1. List of Persons Contacted

<u>Name</u>	<u>Title</u>
D. Precht	Plant Manager
S. Armstrong	Operations Manager
D. Baustert	Pellet Operations Manager
M. Rosser	EHS Manager
C. Snyder	EHS Engineering Manager
G. Couture	EHS Licensing and Regulatory
D. Graham	EHS Engineering
R. Taylor	EHS Engineering
J. Peterson	Site Maintenance Manager
R. Bates	Maintenance and Equipment Improvement

2. List of Items Opened, Closed, and Discussed

Item Number	Status	Description
EEI 70-1151/2011-004-01	Open	Failure to remove from service defective sling, IROFS UF6CYL-110
VIO 70-1151/2010-014-01	Closed	Escalated Enforcement: IFBA Filter Press
URI 70-1151/2009-005-01	Closed	The failure to maintain current knowledge of the special nuclear material in Item B85403
VIO 70-1151/2011-002-01	Closed	Failure to ensure that a criticality in a cylinder in the vaporizer was highly unlikely
URI 70-1151/2011-002-02	Closed	Leak testing of backflow prevention valves
LER 70-1151/2011-001-0	Closed	Certificate of Compliance USA/9291/B(U)-F96, Liqui-Rad Transport Unit Package not observed in making a shipment
LER 70-1151/2011-002-0	Closed	Certificate of Compliance USA/9196/B(U)-F96, UX-30 Package
LER 70-1151/2010-004-0	Closed	Unanalyzed condition in the IFBA waste water system Event 46122