

REGULATOR INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:8105270420 DOC.DATE: 81/05/20 NOTARIZED: NO DOCKET #
 FACIL:50-263 Monticello Nuclear Generating Plant, Northern States 05000263
 AUTH.NAME AUTHOR AFFILIATION
 MAYER,L.O. Northern States Power Co.
 RECIP.NAME RECIPIENT AFFILIATION
 KEPPLER,J.G. Region 3,Chicago, Office of the Director

SUBJECT: Forwards LERs 81-006/01T-0,81-007/01T-0,81-011/01T-0 &
 81-012/01T-0.

DISTRIBUTION CODE: A002S COPIES RECEIVED:LTR 1 ENCL 1 SIZE: 1+9
 TITLE: Incident Reports

NOTES:

ACTION:	RECIPIENT ID CODE/NAME	COPIES		RECIPIENT ID CODE/NAME	COPIES	
		LTTR	ENCL		LTTR	ENCL
	IPPOLITO,T. 04	3	3			
INTERNAL:	A/D COMP&STRU06	1	1	A/D ENV TECH 07	1	1
	A/D MATL & QU08	1	1	A/D OP REACT009	1	1
	A/D PLANT SYS10	1	1	A/D RAD PROT 11	1	1
	A/D SFTY ASSE12	1	1	ACC EVAL BR 14	1	1
	AEOD	3	3	AEOD/DMU	3	3
	ASLBP/J.HARD	1	1	AUX SYS BR 15	1	1
	CHEM ENG BR 16	1	1	CONT SYS BR 17	1	1
	CORE PERF BR 18	1	1	DIR,ENGINEERI20	1	1
	DIR,HUM FAC S21	1	1	DIR,SYS INTEG22	1	1
	EFF TR SYS BR23	1	1	EQUIP QUAL BR25	1	1
	GEOSCIENCES 26	1	1	I&C SYS BR 29	1	1
	I&E 05	1	1	JORDAN,E./IE	1	1
	LIC GUID BR 30	1	1	MATL ENG BR 32	1	1
	MECH ENG BR 33	1	1	NRC PDR 02	1	1
	OR ASSESS BR 35	1	1	POWER SYS BR 36	1	1
	RAD ASSESS BR39	1	1	REACT SYS BR 40	1	1
	REG FILE 01	1	1	REL & RISK A 41	1	1
	SFTY PROG EVA42	1	1	STRUCT ENG BR44	1	1
EXTERNAL:	ACRS 46	16	16	INPO,J.STEARNS	1	1
	LPDR 03	1	1	NSIC 05	1	1

MAY 28 1981

TOTAL NUMBER OF COPIES REQUIRED: LTTR 62 ENCL 62

LJ




Northern States Power Company

414 Nicollet Mall
Minneapolis, Minnesota 55401
Telephone (612) 330-5500

May 20, 1981

Mr J G Keppler
Office of Inspection & Enforcement
U S Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, IL 60137



MONTICELLO NUCLEAR GENERATING PLANT
Docket No. 50-263 License No. DPR-22

Type B Containment Leakage Test Failures
RO-80-6, 7, 11, and 12

Three copies of the Licensee Event Reports for these occurrence are attached.

These events are reported in compliance with Technical Specification 6.7.B.2.d since they represent degradation of containment isolation valves.

David Musoffson

L O Mayer, PE
Manager of Nuclear Support Services

LOM/DMM/jh

cc: Director, IE, USNRC (30)
Director, MIPC, USNRC (3)
NRC Resident Inspector
MPCA
Attn: J W Ferman

A002
3
1/1

5

8105270 420