REGULARY INFORMATION DISTRIBUTIO SYSTEM (RIDS)

ACCESSION NBR:8009300234 DOC.DATE: 80/09/25 NOTARIZED: NO DOCKET # FACIL:50-263 Monticello Nuclear Generating Plant, Northern States 05000263

AUTH.NAME AUTHOR AFFILIATION

WARD, E.C.

Northern States Power Co.

RECIP.NAME

RECIPIENT AFFILIATION

KEPPLER, J.G.

Region 3, Chicago, Office of the Director

SUBJECT: Errata to "Environ Monitoring & Ecological Studies Program Rept, 1979." Figures 2.2-3 through - 7 have drafting error in legend. Solid line should be identified as Sector A & dashed line as Sector B.

DISTRIBUTION CODE: A007S COPIES RECEIVED:LTR FINCLO SIZE: TITLE: Periodic Environmental Monitoring Rpts (Annual, Semi-Annu

NOTES:

	RECIPIENT ID CODE/NAM	E	COPIES LITTE EN	ICL	RECIPIEN ID CODE/N		COPI LTTR	
ACTION:	IPPOLITO,T.	04	7	1				1
INTERNAL:	ENV ENG BR	80	1 :		I&E:	06	2	k
	NRC PDR	2 0	1	1	OMPA-HARTE	IELD	1	1
	OR ASSESS BR	09	1		RAD ASSESS	BR10	1	
a	REG FILE	01	1	1				189
EXTERNAL:	ACRS	11	1	1	LPDR	03	1	19
	NSIC	05	1.	1			,	

00T 1 1980



NSP

NORTHERN STATES POWER COMPANY

MINNEAPOLIS, MINNESOTA 55401

September 25, 1980

Mr J G Keppler, Director, Region III Office of Inspection & Enforcement U S Nuclear Regulatory Commission 799 Roosevelt Road Glen Ellyn, IL 60137

Dear Mr Keppler:

MONTICELLO NUCLEAR GENERATING PLANT Docket No. 50-263 License No. DPR-22

1979 Environmental Monitoring and Ecological Studies Program Report Errata

The subject report submitted with our letter of August 14, 1980 includes the following figures:

Figure 2.2-3	page 2.2-17
- 4	-18
- 5	-19
-6	-20
- 7	- 21

Unfortunately each of these figures has a common drafting error in the legend. The solid line should be identified as "Sector A" and the dashed line should be identified as "Sector B". Please pen in these corrections.

Yours very truly,

E C Ward, PE

Manager-Nuclear Environmental Services

ECW/jh

cc: Director, NRR (c/O DSB) (17)

G Charnoff

MPCA

Attn: J W Ferman NRC Resident Inspector

100/2/0