

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:8812050213 DOC.DATE: 88/11/29 NOTARIZED: NO DOCKET #
 FACIL:50-263 Monticello Nuclear Generating Plant, Northern States 05000263
 AUTH.NAME: AUTHOR AFFILIATION
 HARRISON,J.J. Region 3, Ofc of the Director
 CIP.NAME RECIPIENT AFFILIATION
 HARRISON,C.E. Northern States Power Co.

SUBJECT: Forwards Insp Rept 50-263/88-20 on 881024-28.No violations noted.

DISTRIBUTION CODE: IE01D COPIES RECEIVED:LTR 1 ENCL 1 SIZE: 2+5
 TITLE: General (50 Dkt)-Insp Rept/Notice of Violation Response

NOTES:

	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
	PD3-1 PD	1 1	STEFANO,J	1 1
INTERNAL:	AEOD	1 1	DEDRO	1 1
	NRR MORISSEAU,D	1 1	NRR/DLPQ/PEB 11	1 1
	NRR/DLPQ/QAB 10	1 1	NRR/DOEA DIR 11	1 1
	NRR/DREP/EPB 10	1 1	NRR/DREP/RPB 10	2 2
	NRR/DRIS DIR 9A	1 1	NRR/PMAS/ILRB12	1 1
	NUDOCS-ABSTRACT	1 1	OE LIEBERMAN,J	1 1
	OGC/HDS1	1 1	<u>REG FILE</u> 02	1 1
	RGN3 FILE 01	1 1		
EXTERNAL:	LPDR	1 1	NRC PDR	1 1
	NSIC	1 1	RESL MARTIN,D	1 1

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK,
 ROOM P1-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION
 LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTTR 22 ENCL 22

R
I
D
S
/
A
D
S

R
I
D
S
/
A
D
S

NOV 29 1988

Docket No. 50-263

Northern States Power Company
ATTN: Mr. C. E. Larson
Vice President, Nuclear
Generation
414 Nicollet Mall
Minneapolis, MN 55401

Gentlemen:

This refers to the routine safety inspection conducted by Mr. J. H. Neisler of this office on October 24-28, 1988, of activities at the Monticello Nuclear Generating Station authorized by NRC Operating License No. DPR-22 and to the discussion of our findings with Mr. W. A. Shamla and others of your staff at the conclusion of the inspection. The purpose of the inspection was to examine the implementation of the requirements of Generic Letter 83-28.

The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

No violations of NRC requirements were identified during the course of this inspection.

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter and the enclosed inspection report will be placed in the NRC Public Document Room.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

Original Signed by J. J. Harrison

J. J. Harrison, Chief
Engineering Branch

8812050213 881129
PDR ADDCK 05000263
Q PNU

Enclosure: Inspection Report.
No. 50-263/88020(DRS)

See Attached Distribution

RIII
Nesler/jk
11/29/88
yjs

RIII
Jackiw
11/24/88

RIII
Gardner
11/24/88

RIII
Harrison
11/29/88

DEO

NOV 29 1988

Distribution

cc w/enclosure:

W. A. Shamla, Plant Manager

DCD/DCB (RIDS)

Licensing Fee Management Branch

Resident Inspector, RIII Monticello

Resident Inspector, RIII Prairie
Island

John W. Ferman, Ph.D.,

Nuclear Engineer, MPCA