

DCD/DCB  
(RIDS)

APR 19 1990

Docket No. 50-263

Northern States Power Company  
ATTN: Mr. C. E. Larson  
Vice President, Nuclear  
Generation  
P.O. Box 59040  
Minneapolis, MN 55459-0040

Gentlemen:

This refers to the routine safety inspection conducted by Messrs. J. Hard, P. Moore, and D. Schrum of this office on February 18 through March 31, 1990 of activities at the Monticello Nuclear Generating Station authorized by NRC Operating License No. DPR-22 and to the discussion of our findings with Mr. D. Antony at the conclusion of the inspection.

The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

No violations of NRC requirements were identified during the course of this inspection.

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter, the enclosures, and your response to this letter will be placed in the NRC Public Document Room.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

H. B. Clayton, Chief  
Reactor Projects Branch 2

Enclosure: Inspection Report  
No. 50-263/90006(DRP)

See Attached Distribution

RIII  
RWD  
Schrum/lms  
4/18

RIII  
RWD  
DeFayette  
4/18

Yes  
RIII  
Clayton  
4/18/90

9005110206 900419  
PDR ADOCK 05000263  
Q FDC

TEO  
111

APR 19 1980

Northern States Power Company

2

Distribution

cc w/enclosure:

D. D. Antony, Plant Manager

DCD/DCB (RIDS)

Licensing Fee Management Branch

Resident Inspector, RIII Monticello

Resident Inspector, RIII Prairie  
Island

John W. Ferman, Ph.D.,

Nuclear Engineer, MPCA

State Liaison Officer, State

of Minnesota Docket No. 50-263

William Long, LPM, NRR