



Northern States Power Company

414 Nicollet Mall
Minneapolis, Minnesota 55401-1927
Telephone (612) 330-5500

September 11, 1990

A Bert Davis
Regional Administrator, Region III
U S Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, Illinois 60137

PRIORITY ROUTING	
First	Second
RA	RC
ORA	ETZ
DRP	SZA
DRS	WL
DRSS	OL
DRWA	NO
	PAO

FILE

MONTICELLO NUCLEAR GENERATING PLANT
DOCKET NO 50-263 LICENSE NO DPR-22

Response to
Systematic Assessment of Licensee Performance
(SALP) Inspection Report No 50-263/90001

Reference: Letter dated August 28, 1990 from A Bert Davis, Regional Administrator, Region III, NRC, to L R Eliason with SALP 9 Board Report, Inspection Report No. 50-263/90001

Your letter dated August 28, 1990 solicited written comments related to the Systematic Assessment of Licensee Performance (SALP) Board Report covering the period March 1, 1989 through June 30, 1990 (SALP 9).

The SALP 9 Report was the subject of a public meeting held at the Monticello Training Center on September 11, 1990. We have no additional comments to offer related to the SALP 9 Report.

As we noted at the September 11, 1990 meeting, we appreciate the feedback the SALP process provides related to operation of our nuclear generating plants. The analyses provided in the SALP 9 Report will be used to strengthen those areas where weaknesses are evident and provide further improvements in those areas in which we performed strongly.

Leon R Eliason
Vice President
Nuclear Generation

c: Sr Resident Inspector, NRC
NRR Project Manager, NRC
G Charnoff

SEP 12 1990

9009240148 900914
PDR ADCK 05000263
Q PDC