



P.O. Box 330838 Kahului, HI. 96733

Phone (808) 877-2755 Fax: (808) 877-0438

RECEIVED

OCT 14 2011

DNMS

October 13, 2011

Nuclear Materials Licensing Branch
U.C. Nuclear Regulatory Commission, Region IV
612 East Lamar Blvd., Suite 400
Arlington, Texas 76011-4125

RE: N.R.C. License Amendment Request
License No. 53-29069-01
Docket No. 030-33548

Dear Sir or Madam,

We would like to amend our N.R.C. License, No. 53-29069-01 to more accurately reflect the current status of our Radiation Safety Program.

We request to have CPN International, Inc, Model – MC series removed under paragraph 9, "Authorized use" from our license. (See attachment)

Should you have any questions concerning this matter, please feel free to contact me at (808) 268-8350.

Respectfully yours,

A handwritten signature in black ink, appearing to read 'Ron Aroyan', with a horizontal line extending to the right.

Ron Aroyan
Superintendent
Maui Paving, LLC

Ma 576196



Troxler Electronic Laboratories, Inc. - Troxler International, Ltd.
3008 Cornwalie Road, P.O. Box 12057, Research Triangle Park, NC 27709 - USA
Telephone: 919/549-8861 Telefax: 919/549/0781

September 20, 2010

Grace Pacific Corporation
Attn: Felicia Souza
PO Box 78
Honolulu, HI 96810

[Ref. ML080720340]

Attn: Felicia Souza

This is to acknowledge receipt and transfer of ownership of the nuclear gauge(s) listed below, and the radioactive sources contained therein, to Troxler under North Carolina Radioactive Material License #032-0182-1. You should retain this letter in your files for future reference.

Date Received: 09-13-10

Job Number
14228

Model
CPN MC-3

Serial Number
M390605145

Regards,

Emily Davis
Service/Repair Department
Troxler Electronics

CPN International - InstroTek
4057 Port Chicago Hwy, Ste. 100
Concord, CA 94520
925-363-9770, Fax 925-363-9385

5/25/2010
Test Number: 3

Felicia Soliza
Grace Pacific Corporation
P.O. Box 78
Honolulu, HI 96810

Phone: (808)479-5669
Fax: (808)672-8619

LEAK TEST CERTIFICATE

CA Materials License #1100-07

This certifies that leak test analysis was conducted on the sample with the following information. The results shown below accurately represent the level of removable contamination.

Gauge Model: MC-3
Gauge S/N: M390605145

Test Date: 5/19/2010

Source (Model/Serial#)	Reading in microCuries
Am-241/Be	0.00002
Cs-137	0.00000

Note: 0.005 microCuries (185 Bq) or greater is considered a leaking source.° The source(s) tested above may remain in use.

Reviewed by: _____



Date: _____

5-25-10

Customer Signature: _____

Date: _____

°CPN gauges are 50 mCi Am241:Be and 10 mCi Cs-137. Humboldt gauges are 40 mCi Am241:Be and 10 mCi Cs-137. InstroTek Gauge is 40 mCi Am241:Be and 10 mCi Cs-137. Troxler gauges all, except 4640, are 40 mCi Am241:Be and 8 mCi Cs-137. Troxler 4640 is 8 mCi Cs-137.

h 576196

BETWEEN:

Accounts Receivable/Payable
and
Regional Licensing Branches

[FOR ARPB USE]
INFORMATION FROM LTS

Program Code: 03121
Status Code: Pending Amendment
Fee Category: 3P
Exp. Date: 09/30/2014
Fee Comments:
Decom Fin Assur Reqd: N

License Fee Worksheet - License Fee Transmittal

A. REGION

1. APPLICATION ATTACHED

Applicant/Licensee: MAUI PAVING, LLC
Received Date: 10/14/2011
Docket Number: 3033548
Mail Control Number: 576196
License Number: 53-29069-01
Action Type: Amendment

2. FEE ATTACHED

Amount: _____
Check No.: _____

3. COMMENTS

Signed: Colleen Murchan

Date: 10-14-11

B. LICENSE FEE MANAGEMENT BRANCH (Check when milestone 03 is entered / /)

1. Fee Category and Amount: _____

2. Correct Fee Paid. Application may be processed for:

Amendment: _____

Renewal: _____

License: _____

3. OTHER _____

Signed: _____

Date: _____