NRC FÓRM 591M PART 1		U	.S. NUCLEAR REGULATO	RY COMMISSION
M0 CFR 2.201	ETY INSPECTION REPORT	AND COMPLIANCE IN	ISPECTION	
LICENSEE/LOCATION INSPECTED: RSA Laboratories A Division of Radiation Associates, Inc. 19 and 21 Pendleton Drive Hebron, Connecticut 06248 REPORT Nos 2011-001		2. NRC/REGIONAL OFFICE U.S. Nuclear Regulatory Commission Region I, 475 Allendale Road King of Prussia, Pennsylvania 19406-1415		
3. DOCKET NUMBER(S) 030-33025	4. LICENSE NUMBER(S 06-30007-01	5)	5. DATE(S) OF INSPECT Nov. 15, 21, and 23	
LICENSEE:	00 00001 01		7,011,10,21, 0,10,21	
The violation(s), specification identified, non-repetitive, and 1600, to exercise discretion, Non-Cited Violation 4. During this inspection ce	les and regulations and the condition ecords, interviews with personnel, and findings, no violations were identified ed. ally described to you by the inspector d corrective action was or is being tak	s of your license. The inspect observations by the inspect observations by the inspect of the inspect of the following requirement (s) the following require	ction consisted of selective for. The inspection findings on the inspection findings of the inspection	examinations of are as follows: y were self- Policy, NUREG-
	Statement of Co	rrective Actions		
I hereby state that, within 30 days, the corrective actions is made in accordar date when full compliance will be achi	nce with the requirements of 10 CFR	2.201 (corrective steps alrea	dy taken, corrective steps v	vhich will be taken,
Title	Printed Name		Signature	Date
LICENSEE'S REPRESENTATIVE				
NRC INSPECTOR	Garage CA	DAIN		11/30/11
BRANCH CHIEF	Judith A. Jon	Event -to	that Jour	11/30/11
*591M PART 1 (RI Rev. 08/10/2011	. 0	G:\Reference\	Word 2007 blank forms\Blan	nk 591M-Part1.doc
SUNSI Review Completed By:	/RA/ FCC		X Public X	Non-Sensitive
This doc	ument becomes an NRC Official Agen	ey Record once it is signed by	the Branch Chief	1-00d