

December 21, 2011

Mr. Michael Kiley, Vice President
Florida Power & Light Company
Turkey Point Nuclear Generating Station
9760 SW 344th Street
Homestead, FL 33035

SUBJECT: TURKEY POINT NUCLEAR GENERATING STATION, UNITS 3 AND 4 – NRC
SECURITY INSPECTION REPORT 05000250/2011201 AND
05000251/2011201

Dear Mr. Kiley:

On November 14, 2011, the U.S. Nuclear Regulatory Commission (NRC) completed a security baseline inspection at the Turkey Point Nuclear Generating Station, Units 3 and 4. The inspection covered one or more of the key attributes of the security cornerstone of the NRC's Reactor Oversight Process. The enclosed inspection report documents the inspection results, which were discussed on November 17, 2011, with you and other members of your staff.

The inspection examined activities conducted under your license as they relate to security and compliance with the Commission's rules and regulations and with the conditions of your license. The inspectors reviewed selected procedures and records, observed activities, and interviewed personnel.

Based on the results of this inspection, no findings of significance were identified.

In accordance with Title 10 of the *Code of Federal Regulations* (10 CFR) 2.390 of the NRC's "Rules of Practice," a copy of this letter will be available electronically for public inspection in the NRC Public Document Room or from the Publicly Available Records component of NRC's Agencywide Documents Access and Management System (ADAMS). ADAMS is accessible from the NRC Website at <http://www.nrc.gov/reading-rm/adams.html> (the Public Electronic Reading Room). However, because of the security-related information contained in the enclosure, and in accordance with 10 CFR 2.390, a copy of this letter's enclosure will not be available for public inspection.

In accordance with 10 CFR 2.390(b)(1)(ii), the NRC is waiving the affidavit requirements for your response, if any. This practice will ensure that your response will not be made available electronically for public inspection in the NRC Public Document Room or from the NRC's document system, ADAMS. If Safeguards Information is necessary to provide an acceptable response, please provide the level of protection described in 10 CFR 73.21. Otherwise, mark

The enclosure transmitted herewith contains SUNSI. When separated from the enclosure, this transmittal document is decontrolled.
--

~~OFFICIAL USE ONLY – SECURITY-RELATED INFORMATION~~

M. Kiley

-2-

your entire response “Security-Related Information - Withhold Under 10 CFR 2.390” and follow the instructions for withholding in 10 CFR 2.390(b)(1).

Sincerely,

/RA/

Garmon West, Chief
Security Training and Support Branch
Division of Security Operations
Office of Nuclear Security and Incident Response

Docket Nos.: 50-250, 50-251
License Nos.: DPR-31, DPR-41

Enclosure: Inspection Report No. 05000250/2011201 and 05000251/2011201 w/ Attachments:
Supplemental Information

~~OFFICIAL USE ONLY – SECURITY-RELATED INFORMATION~~

~~OFFICIAL USE ONLY – SECURITY-RELATED INFORMATION~~

M. Kiley

-2-

your entire response "Security-Related Information - Withhold Under 10 CFR 2.390" and follow the instructions for withholding in 10 CFR 2.390(b)(1).

Sincerely,

/RA/

Garmon West, Chief
Security Training and Support Branch
Division of Security Operations
Office of Nuclear Security and Incident Response

Docket Nos.: 50-250, 50-251
License Nos.: DPR-31, DPR-41

Enclosure: Inspection Report No. 05000250/2011201 and 05000251/2011201 w/ Attachments:
Supplemental Information

DISTRIBUTION:

R. Albert, NSIR
M. Buckley, NSIR
S. Coker, NSIR
C. Johnson, NSIR
D. Johnson, NSIR

C. Keon, NSIR
D. Willis, NSIR
M. Maley, NSIR
T. Howard, NSIR
L. Trocine, OEDO

J. Trapp, RI
M. Ernstes, RIII
R. Skokowski
M. Hay, RIV

HARD COPY W/ ENCL:

J. Curry, NSIR

ADAMS PACKAGE NO.: ML11343A043

Letter: ML11343A044

Enclosure: ML11343A045

OFFICE	NSIR/DSO/STSB	NSIR/DSO/STSB	NSIR/DSO/STSB	NSIR/DSO/STSB
NAME	M. Maley	J. Curry	M. Buckley	G. West
DATE	12/1/11	12/12/11	12/13/11	12/21/11

OFFICIAL RECORD COPY