



REPLY TO  
ATTENTION OF

DEPARTMENT OF THE ARMY  
HEADQUARTERS, FORT BELVOIR COMMUNITY HOSPITAL  
9300 DEWITT LOOP  
FORT BELVOIR, VIRGINIA 22060-5901

January 23, 2012

Health Physics Service

K-8

Nuclear Regulatory Commission, Region 1  
Medical Licensing Division  
ATTN: Ms. Betsy Ullrich/Mr. James P. Dwyer  
475 Allendale Road  
King of Prussia, Pennsylvania 19406-1415


Dear Sir or Madam:

As required in Title 10, Code of Federal Regulation Part 30 and Part 35, we are requesting an amendment to our NRC License Number ~~08-01738-03~~ Docket Number: 03001317 / Control Number: 574899, Condition 10, for the following reason: 08-01738-02

Due to an administrative error, the building number for the Fort Belvoir Community Hospital needs to be changed on our license from Building 1240 to Building 1230. This change is to ensure that upon decommissioning of the hospital at some date in the future that Building 1240 is not required to meet whatever regulatory requirements that may exist for the removal of radioactive material. Building 1240 is not now nor ever expected to be utilized for the storage or use of radioactive material.

For additional information, please contact Lieutenant Colonel Francis Fota, Radiation Safety Officer at 571-231-4029 (email [francis.fota@us.army.mil](mailto:francis.fota@us.army.mil)) or Colonel Casmere H. Taylor, JTF-CAPMED Radiation Hygiene Consultant at 301-400-2539 (email [casmere.taylor@med.navy.mil](mailto:casmere.taylor@med.navy.mil)).

Sincerely,

  
Susan Annicelli  
Colonel, US Army  
Commanding

576840  
NMSS/RGN1 MATERIALS-002

This is to acknowledge the receipt of your letter/application dated

1/23/2012, and to inform you that the initial processing which includes an administrative review has been performed.

Amendment (08-01738-02)  
There were no administrative omissions. Your application was assigned to a technical reviewer. Please note that the technical review may identify additional omissions or require additional information.

Please provide to this office within 30 days of your receipt of this card

---

A copy of your action has been forwarded to our License Fee & Accounts Receivable Branch, who will contact you separately if there is a fee issue involved.

Your action has been assigned **Mail Control Number** 576840.  
When calling to inquire about this action, please refer to this control number.  
You may call us on (610) 337-5398, or 337-5260.