

**SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION**

1. LICENSEE/LOCATION INSPECTED: Cottage Grove Cardiology, PC 711 Cottage Grove Road Bloomfield, CT 06002  REPORT NUMBER(S)                      2012001	2. NRC/REGIONAL OFFICE  <b>U.S. Nuclear Regulatory Commission                  Region I, 475 Allendale Road                  King of Prussia, Pennsylvania 19406-1415</b>	
3. DOCKET NUMBER(S) 030-34007	4. LICENSE NUMBER(S) 06-30260-01	5. DATE(S) OF INSPECTION March 23, 2012

**LICENSEE:**

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:

1. Based on the inspection findings, no violations were identified.

2. Previous violation(s) closed.

3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, to exercise discretion, were satisfied.

Non-cited violation(s) were discussed involving the following requirement(s) and corrective action(s):

\_\_\_\_\_

4. During this inspection, certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited in accordance with the NRC Enforcement Policy. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11. (Violations and Corrective Actions)

*10 CFR 20.1801 requires that the licensee shall secure from unauthorized removal or access licensed materials that are stored in controlled or unrestricted areas. Contrary to the above, on March 23, 2012, for several minutes the licensee left 82mCi of Tc99m and 142 uCi of Cs137 in the hot lab unsecured and unattended. The licensee immediately locked the hot room door and committed to keep the door locked when unattended.*

**Statement of Corrective Actions**

I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

Title	Printed Name	Signature	Date
LICENSEE'S REPRESENTATIVE	Carolyn M Kosack MD	<i>Carolyn M Kosack MD</i>	3/29/2012
NRC INSPECTOR	Robin Elliott	<i>Robin Elliott</i>	3/23/2012
BRANCH CHIEF	JOSEPH NICK	<i>Joseph Nick</i>	3/29/12

SUNSI Review Completed By: IRA/ Robin Elliott

Public     Non-Sensitive