

**SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION**



<p>1. LICENSEE/LOCATION INSPECTED:                  University of Idaho                  Environmental Health and Safety                  1108 West Sixth Street                  Moscow, Idaho 83844-2030                  Location: Idaho Falls Research Extension Center &amp; Idaho State University/University of Idaho Center for Higher Education-1776 Science Center Drive, Idaho Falls, Idaho                  REPORT NO: 030-32323/2012-003</p>	<p>2. NRC/REGIONAL OFFICE                   U.S. Nuclear Regulatory Commission                  Region IV, 1600 East Lamar Boulevard                  Arlington, Texas 76011-4511</p>	
<p>3. DOCKET NUMBER 030-32323</p>	<p>4. LICENSE NUMBER 11-27382-01</p>	<p>5. DATE OF INSPECTION May 08, 2012</p>

**LICENSEE:**  
 The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:

- 1. Based on the inspection findings, no violations were identified.
- 2. Previous violation(s) closed.
- 3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy to exercise discretion, were satisfied.
  - Non-Cited Violation(s) was/were discussed involving the following requirement(s) and Corrective Action(s):
- 4. During this inspection certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.

**Licensee's Statement of Corrective Actions for Item 4, above.**

I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

Title	Printed Name	Signature	Date
LICENSEE'S REPRESENTATIVE			
NRC INSPECTOR	R. Rick Muñoz		05/14/2012
BRANCH CHIEF	G. Michael Vasquez		5/22/12

**Munoz, Rick**

---

**From:** Munoz, Rick  
**Sent:** Wednesday, May 16, 2012 10:07 AM  
**To:** samir@uidaho.edu  
**Cc:** Munoz, Rick  
**Subject:** NRC Inspection Reports 002, 003, & 004  
**Attachments:** UNIVERSITY OF IDAHO - IDAHO FALLS - IR003.pdf; UNIVERSITY OF IDAHO - KIMBERLY - IR004.pdf; UNIVERSITY OF IDAHO - ABERDEEN - IR002.pdf

Samir,

Attached are NRC form 591s which document inspection numbers 002, 003, and 004 which were conducted in Idaho Falls, Aberdeen, and Kimberly, Idaho during the week of May 7-11, 2012. If you have any questions please feel free to contact me.

Kindest Regards,

Rick Muñoz  
Nuclear Materials Inspector  
NRC Region-IV  
1600 East Lamar Boulevard  
Arlington, TX 76011-4511

Office: (817) 200-1220  
Cell: (512) 773-8520  
Fax: (817) 200-1188



\*\*\*\*\*  
The information contained in this message may be privileged and/or confidential and protected from disclosure. If the reader of this message is not the intended recipient, or an employee or agent responsible for delivering this message to the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please notify the sender immediately by replying to the message and deleting the material from any computer.

Note: Any views or opinions presented in this message are solely those of the author and do not necessarily represent those of the Nuclear Regulatory Commission, Region-IV or the Nuclear Materials Safety Branch-A. All e-mails are subject to monitoring and archival.

Finally, the recipient should check this message and any attachments for the presence of viruses. The Nuclear Regulatory Commission accepts no liability for any damage caused by any virus transmitted by this e-mail.

\*\*\*\*\*