Attachment 9 to GNRO-2012/00039

Attachment 9 to

GNRO-2012/00039

Entergy Nuclear Grand Gulf Nuclear Station License Renewal Environmental Audit

- Hydrology Patton - Attachment L labeled

"Reporting Documentation - Unit 2 Sumps"

Attachment L

Reporting Documentation – Unit 2 Sumps

01-S-06-5	Revision: 108							
Attachment II	Page 1 of 2							

				L				·	
									PAGE 1 OF 2
NRC FORM 361 (12-2008)		EVENT I		OR PLANT TION WORK	SHE		OP	REGULATOR CI	
NRC OPERATION TELEPHIZED 301-415-0550 and [3r		VRY - 301-81	6-5100 or 800-5	332-3469°, BACKUP *Licensess who m					lephone numbers.
	ACILITY OR ORGANIZATION		UNIT	NAME OF CALLER				CALL BACK #	
124ZEDT C	inal Guls Ni Station	sclear	1	Frank	we	iver		601-43	37-2374
EVENT TIME A ZONE EN	VENT DATE	POWERMODE	BEFORE			POWERMOD	AFTER		
0852 CDT	4/29/11	96%	6 / Mo.	DE		96	7 /	MODE	1
EVENT CLASS	FICATIONS	1-Hr. No	n-Emergenc	10 CFR 50.72(b	<u>(1)</u>	(v)(A)	Sale S/D (Capability	ANA
GENERAL BARROBNOY	CENIMARC		TS Devistion		ADEV	(v)(B)	RHIR Caps	billy	ANO
SITE AREA EMERGENCY	SITIAARC	4-Hr. No	n-Emergenc	10 CFR 50.72(b)	(2)	(v)(C)	Control of	Red Release	AINC
ALERT	ALEXAGEC	(0)	TS Required S/D		ASHU	(A)(D)	Accident N	Vitigation	AND
UNUSUAL EVENT	UNUMARC	(iv)(A)	BCCS Discharge to	RC8	ACCS	(xii)	Offsite Me		AMED
T STIS NON-ENERGENCY	(see next columns)		RPS Actuation (scr		ARPS	(xiii)		m/Asmt/Reep	ACCM
PHYSICAL SECURITY (73.7	1) 0000		Officia Notification		AFFE	60-0		onal 10 CFR	
MATERIALIDIPOSURE	577 1			10 CFR 50.72(b)				ecilied System A	
FITNESS POR DUTY	Hना		Degraded Condition		A080	Other U	napecifi	ed Requirer	nent (identify)
OTHER UNGFEDFED RECM		1.71-	Jnenslyzed Condit		ALNA				NONR
INFORMATION ONLY	W	(M)(A) 5	Specified System		ARSF				NONR
•			DESC	RIPTION					

On 4/28/2011 GGNS Unit 2 turbine building sump samples indicated tritium presence. The Unit 2 turbine building is an abandoned, partially constructed building. Follow-up review and investigation confirmed that water from unit 2 turbine building sump had been pumped to the environment through installed sump pumps and piping connected between the sumps and roof drains on the unit 2 turbine building. The release has been terminated by turning off the sump pumps located in the unit 2 turbine building. Site procedures require notification of off-site agencies, therefore the NRC is being notified in

NOTIFICATIONS YES NO WILL BE ANYTHING UNUSUAL OR NOT UNDERSTOOD? NOT UNDERSTOOD? STATE(s) LOCAL OTHER GOV AGENCIES YES (Explain above) NO (Explain above) NO (Explain above) ADDITIONAL INFO ON SACK							
NRC RESIDENT X NOT UNDERSTOOD? STATE(s) X DID ALL SYSTEMS LOCAL X FUNCTION AS REQUIRED? OTHER GOV AGENCIES X MODE OF OPERATION ESTIMATED ADDITIONAL INFO ON BACK	NOTIFICATIONS	YES	NO	WILL BE	ANYTHING UNUSUAL OR	Street and the street	
COTHER GOV AGENCIES X PUNCTION AS REQUIRED? OTHER GOV AGENCIES X MODE OF OPERATION 1 ESTIMATED ADDITIONAL INFO ON BACK	NRC RESIDENT	X				20 TES (Exprain above)	U WO
OTHER GOV AGENCIES X MODE OF OPERATION 1 ESTIMATED , ADDITIONAL INFO ON BACK	STATE(s)			X	DID ALL SYSTEMS	N v=a	NO (Soulet shows)
OTHER GOV AGENCIES MODE OF OPERATION (ESTIMATED)	LOCAL		X		FUNCTION AS REQUIRED?	∠ , ies	
The second secon	OTHER GOV AGENCIES			Ī	MODE OF OPERATION	ESTIMATED .	ADDITIONAL INFO ON BACK
MEDIAPRESS RELEASE X Unit CONTROL	MEDIA/PRESS RELEASE		X		UNTIL CORRECTED	RESTART DATE: NA	(□ ves ⊠ vo

NRC FORM 361 (12-2000)

PHINTED ON RECYCLED PAPE



accordance with 10CFR50.72 (b)(2)(xi).

01-5-06-5	Revision: 108
Attachment II	Page 2 of 2

RADIOLOGICAL PELE	ASES: C	HECK OR FELL IN	APPLICAT	ADDITIONAL INFO		ejezolen	ellone sho	uid i	be covered	in even	desario	PACE 2 C
LIQUIO RELEASE		EOUS RELEASE		ANNED RELEASE			RELEASE		ONGOING			INATED
MONITORED	UNA	IONITORED	OFFS	ITE RELEASE	T.:	S. EXCE	EDED	\Box	RM ALARA	48	ARE	S EVACUAT
PERSONNEL EXPOS	ED OR (CONTAMINATED	OFFS	ITE PROTECTIVE	ACTION	S RECO	MMENDED		*State releas	e peth in d	neoription	
		Release Rate (Cl/sec)	% T. S. LIMIT		GUIDE	Total A	ctiv	Hy (CI)	% T. S	LIMIT	HOO GUIL
lobie Gile						Viec					~	1000 CI
odine Particulate				 	1 uC	Cl/sec				<u></u>		0.01 Cl
iquid (excluding tritle fesohred noble issued	an and					1/min						0.1 Cl
terofred roofs tracest Iquid (tritum)		} _			0.2 C							5 CI
otal Activity								_				
		PLANT STACK	CON	Denservar eje	CTOR	MAIN	STEAM LI		SG BL	OWDOW	M	OTHER
AD MONITOR READIN	38											
ARM SETPOINTS	_/											
T. S. LIMIT (If applies	eb/aj											·····
S OR SG TUBE LEAK	& CHE	CK ON EST I IN APP	I ICARLE	TEMP (specific)		mieneti	one should	ha i	covered in	event de	e crintin	- I
CATION OF THE LEAK (e.g.			LANGLE	remar (specific o		present.	25 51065	-	.070 00 07	*****	ec peu	9
····												
AKRATE		UNITS: gom/gby	7. S. LIM	118		SUCCO	OR LONG-TER	M DE	VELOPMENT			
K START DATE	1	TIME			WRY				SI	BOONDAR	,	
			AND UNI									
					\							
					\		,		•			
								\				
								•				
									·			
										·		



§ 50.72(b)(2)(xi)

"Any event or situation, related to the health and safety of the public or on-site personnel, or protection of the environment, for which a news release is planned or notification to other government agencies has been or will be made. Such an event may include an on-site fatality or inadvertent release of radioactively contaminated materials."

Provide the following information to the NRC:

 Estimate when the leak/spill started? (Give range of dates, or is it unknown?)

Unknown

- Date and time sample(s) confirmed a leak or spill (or discovery of contamination).
- 4/29/11, 08:52 confirmation of a path to storm drains. Sample was collected and confirmed on 4/28/11 18:45
 - o Is the leak/spill/source known?
- Water sample was from U2 (unfinished construction, non-functioning unit)
 Turbine Bld Sump. This location is inside the Protected Area. Source unknown.
 - o Is this an on-going leak or has the leak source been terminated?
- Leak was terminated on 4/28/11, prior to confirming water flow path to storm drain.
 - Radionuclide concentrations in spill/leak source or origin of the contamination.
- Origin is the U2 Turbine Bld Sumps, 87' elevation. 106,400 pCi/L Tritium in East sump, 100,259 pCi/L Tritium in West sump
 - o Estimated leak rate?
- Unknown, temporary pump was in auto.
 - Has any radioactive material from this spill/leak/event reached the unrestricted area?

- These sumps pump to storm drains, which flow to Outfall 007 which is sampled monthly. There have been no Outfall 007 sample results that have met reportability thresholds in the last 2 years.
 - o What is the estimated volume of plume and curie content of plume?
- N/A, this was a liquid flow path
 - o Radionuclide concentrations in environmental soil and water samples.
- Outfall 007 Sample results December 16, 2010: 723 pCi/L Tritium (error: +/-186.09 pCi/L Tritium)
 - o Does the spill/leak affect ground water, drinking water, or surface water? (Address each one).
- Currently there is no spill/leak so there is no effect on ground water, drinking water, or surface water
 - Could the spill/leak affect ground water, drinking water, or surface water or is the spill/leak likely to affect ground water, drinking water, or surface water?
- Outfall 007 discharges to the Mississippi River so ground water and drinking water could potentially be affected. Surface water will not be affected.
 - Are there monitoring wells down gradient? Activity in down gradient wells?
- Yes there are monitoring wells down gradient. They have tested positive for Tritium but results were below reportable levels. This information is being gathered.
 - o List the distance from the spill/leak to the site boundary/unrestricted area (1) in direction of travel, and (2) nearest boundary.

Approximately 700 m (2) to nearest boundary, the direction of travel (1) is further.

- What is the rate of groundwater movement in the area (e.g., meters per year)?
- This information is being gathered.
 - Estimate of when contaminants will reach the site boundary/unrestricted area.

- The leak/spill has been terminated, so this would have potentially happened in the past.
 - Estimated contaminant concentrations at time when contaminants reach the site boundary. At very least, provide (bounding) estimate of future contaminant concentrations at site boundary relative to 10 CFR 50 Appendix I design objectives.

Highest result for a groundwater monitoring well sample was 11,600 pCi/l on March 2, 2011.

 Are the radionuclide concentrations expected to be below the 10 CFR 20 Appendix B, Table 2 values once the plume reaches the unrestricted area?

This information is being gathered but there have been no results above reportable limits.

o What is the calculated dose to a hypothetical member of the public at the source of the leak/spill if the affected water (ground, drinking, or surface) was a drinking water source. (Calculate this value even if the affected water is not a source of drinking water.) Use any valid method or use a conservatively bounding estimate (e.g., for tritium use the proportionality that 4 mrem annual is equivalent to 20,000 pCi/l annual average concentration.)

Unknown at this time. Based on the last sample of Outfall 007, the calculated dose would be 0.144mrem annual equivalent.

What is the calculated dose to a hypothetical member of the public at the site boundary if the affected water (ground, drinking, or surface) at the site boundary was a drinking water source. (Calculate this value even if the affected water is not a source of drinking water.) Use any valid method or use a conservatively bounding estimate (e.g., for tritium use the proportionality that 4 mrem annual is equivalent to 20,000 pCi/l annual average concentration.)

Unknown at this time.

 Does the utility plan any remediation or cleanup activities at the current time?

Information is being gathered and a decision will be made.

Notifications made for H3.txt

From: Perino, Christina
Sent: Friday, April 29, 2011 4:08 PM
To: RICHEY, MARTY L; Perito, Michael; BROWNING, JEREMY G
Cc: SCARBROUGH, RICHARD A; TRICHELL, WILLIAM T; EHRHARDT, KARL F; Ford,

Bryan

Subject: Notifications made for H3

Contacts made for NEI 07-07 industry ground water protection initiative, via EN-RP-113

Jimmy Carson at Mississippi State Dept of Radiological Health

Jimmy Crellin at MDEQ was not interested in the notification. He stated they did not deal in radiology and said MS State Dept of Rad Health was the right notification to make. He took my contact info and called me back. Said he didn't find anyone interested but we could send an email to the head of pollution control. I will follow up with him.

Gary Uricchio at ANI

NEI email address per EN-RP-113: GW_Notice@NEI.org

NRC 4 hour notification

All required notifications made within requirements

Christina

Sent from my iPad