

2

Hernandez, Pete

**From:** Hernandez, Pete *INVR*  
**Sent:** Friday, October 14, 2011 7:40 AM  
**To:** Zimmerman, Jacob  
**Subject:** RE: 2011-10-13 POP - Davis-Besse Containment Shield Building.docx

Jake

It was a conditional question. After discussion it was decided that if no structural cracks were found through the chipping process, then we would be satisfied. If they were found, then we have to reevaluate. No one expects any cracks to be found. I left the question in place to call out what had been discussed and gave the result in the conclusion section. For clarity, next time I'll put the question and answer together. The expectation right now is that there will be no structural cracks found and this will be a non-issue; we are waiting until the licensee finishes their process; the licensee is unsure how long it will take.

Thanks,

Pete

---

**From:** Zimmerman, Jacob *INVR*  
**Sent:** Thursday, October 13, 2011 5:17 PM  
**To:** Hernandez, Pete  
**Subject:** 2011-10-13 POP - Davis-Besse Containment Shield Building.docx

Pete

Nice job on the POP. I made a couple changes and have one outstanding question. See "Yellow" highlighted text in the attachment. Is that an open question that the Region or NRR tech. staff still?

Thanks  
Jake

*B/2*