

Comanche Peak Nuclear Power Plant, Units 3 & 4

COL Application

Part 2, FSAR




Figure 2.4.12-210 Potentiometric Surface Maps (Sheet 1 of 4)

Comanche Peak Nuclear Power Plant, Units 3 & 4
COL Application
Part 2, FSAR




Figure 2.4.12-210 Potentiometric Surface Maps (Sheet 2 of 4)

Comanche Peak Nuclear Power Plant, Units 3 & 4

COL Application

Part 2, FSAR




Figure 2.4.12-210 Potentiometric Surface Maps (Sheet 3 of 4)

Comanche Peak Nuclear Power Plant, Units 3 & 4

COL Application

Part 2, FSAR




Figure 2.4.12-210 Potentiometric Surface Maps (Sheet 4 of 4)