

Comanche Peak Nuclear Power Plant, Units 3 & 4
 COL Application
 Part 2, FSAR




Figure 2.5.2-215 PGA Rock Seismic Hazard Curves for all Sources and for New Madrid Faults Alone