

Comanche Peak Nuclear Power Plant, Units 3 & 4  
 COL Application  
 Part 2, FSAR




Figure 2.5.2-216 25 Hz Rock Seismic Hazard Curves for all Sources and for New Madrid Faults Alone