

Comanche Peak Nuclear Power Plant, Units 3 & 4
 COL Application
 Part 2, FSAR

1Hz+2.5Hz, 10^{-4}

- ε: 2+
- ε: 1 to 2
- ε: 0 to 1
- ε: -1 to 0
- ε: -2 to -1




Figure 2.5.2-224 Deaggregation of 10^{-4} Rock Hazard for 1 and 2.5 Hz