

Comanche Peak Nuclear Power Plant, Units 3 & 4  
 COL Application  
 Part 2, FSAR

5Hz+10Hz,  $10^{-6}$




Figure 2.5.2-227 Deaggregation of  $10^{-6}$  Rock Hazard for 5 and 10 Hz