

Docket File Information
SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

<p>1. LICENSEE/LOCATION INSPECTED:</p> <p>Hot Shots NM, LLC dba Prestige Imaging Group 303 Quadrangle Drive Bolingbrook, IL 60440</p> <p>REPORT NUMBER(S) 12-01</p>	<p>2. NRC/REGIONAL OFFICE</p> <p>Region III U. S. Nuclear Regulatory Commission 2443 Warrenville Road, Suite 210 Lisle, IL 60532-4352</p>
---	---

<p>3. DOCKET NUMBER(S)</p> <p>150-00012</p>	<p>4. LICENSE NUMBER(S)</p> <p>10 CFR 150.20</p>	<p>5. DATE(S) OF INSPECTION</p> <p>June 28, 2012</p>
---	--	--

<p>6. INSPECTION PROCEDURES USED</p> <p>IP 87130</p>	<p>7. INSPECTION FOCUS AREAS</p> <p>03.01-03.07</p>
--	---

SUPPLEMENTAL INSPECTION INFORMATION

<p>1. PROGRAM CODE(S)</p> <p>02220</p>	<p>2. PRIORITY</p> <p>3</p>	<p>3. LICENSEE CONTACT</p> <p>Sean Waites, Imaging Manager</p>	<p>4. TELEPHONE NUMBER</p> <p>(773) 992-6252</p>
--	-----------------------------	--	--

Main Office Inspection Next Inspection Date: _____

Field Office Inspection _____

Temporary Job Site Inspection 17648 Morse St, Lowell, IN _____

PROGRAM SCOPE

This was a reciprocity inspection of a mobile nuclear medicine service provider based out of Bolingbrook, Illinois. The licensee provides diagnostic imaging services. The licensee performs, on average, 6-8 studies per day at each location. The licensee uses only unit doses received from its sister-company radiopharmacy, also in Bolingbrook, Illinois. Doses were transported from the licensee's base of operations in Illinois to the temporary jobsites.

PERFORMANCE OBSERVATIONS

During this inspection, the inspector interviewed licensee personnel; observed dose preparation; performed independent, confirmatory surveys; and reviewed transportation documentation. The inspector observed two calibrated and operable survey instruments: one for ambient surveys and one for wipe test analyses. Licensee personnel demonstrated daily surveys and weekly wipes. Licensee personnel described patient identification and waste handling procedures. Licensee personnel were knowledgeable of spill procedures and medical event criteria. The inspector observed all personnel wearing appropriate dosimetry.

No violations were identified during this inspection.