

AUG 12 1985

In Reply Refer To:
Docket: 50-285/85-07

Omaha Public Power District
ATTN: R. L. Andrews, Division Manager-
Nuclear Production
1623 Harney Street
Omaha, Nebraska 68102

SUBJECT: SYSTEMATIC ASSESSMENT OF LICENSEE PERFORMANCE (SALP); NRC INSPECTION
REPORT 50-285/85-07

Gentlemen:

This refers to the evaluation conducted on April 16, 1985, for the Fort Calhoun Station, and to your response letter of June 11, 1985.

Your written comments have been reviewed by my staff. The proposed actions are considered responsive to the concerns addressed in the SALP report.

In accordance with Section 2.790 of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations, a copy of this letter and enclosure will be placed in the NRC's Public Document Room.

No reply to this letter is required. Your actions in response to the NRC Systematic Assessment of Licensee Performance will be reviewed during our ongoing and future inspections. Should you have any additional questions, please contact us.

Sincerely,

Handwritten signature
Signed By
R. D. Martin

Robert D. Martin
Regional Administrator

Enclosure:
OPPD SALP Assessment Report
dated June 11, 1985

W. G. Gates, Manager
Fort Calhoun Station
P. O. Box 399
Fort Calhoun, Nebraska 68023

(cont. on next page)

RIV:RPB/B <i>[Signature]</i>	RPB/B <i>[Signature]</i>	RPB <i>[Signature]</i>	DRSP <i>[Signature]</i>	RA <i>[Signature]</i>
MEMurphy/1k	LEMartin	EHJohnson	RPDenise	RD Martin
8/2/85	8/2/85	8/2/85	8/5/85	8/15/85

Omaha Public Power District

-2-

Harry H. Voigt, Esq.
LeBoeuf, Lamb, Leiby & MacRae
1333 New Hampshire Avenue, NW
Washington, DC 20036

Kansas Radiation Control Program Director

Nebraska Radiation Control Program Director

bcc to DMB (IE40)

bcc distrib. by RIV:

RPB

RSB

ALL RRI's

RIV Official Reading File

Records Center, INPO

D. Weiss, LFMB (AR-2015)

EP&RPB

Comm. F. M. Bernthal (MS: H-1149)

M. E. Murphy, RPB/B

R. D. Martin, RA

R. P. Denise, DRSP

J. M. Taylor, D/IE

Chmn. N. J. Palladino (MS: H-1144)

Comm. P. M. Roberts (MS: H-1149)

Comm. J. K. Asselstine (MS: H-1149)

Comm. L. W. Zeck (MS: H-1149)

Omaha Public Power District
1623 Harney Omaha, Nebraska 68102
402/536-4000
June 11, 1985
LIC-85-260

Mr. R. D. Martin
Regional Administrator
U. S. Nuclear Regulatory Commission
Region IV
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76011

RECEIVED
JUN 18 1985


- Reference: (1) Docket 50-285
(2) Letter from R. D. Martin to R. L. Andrews dated May 14, 1985
NRC SALP Board Report 50-285/85-07
(3) Letter from Dorwin R. Hunter to R. L. Andrews dated May 28, 1985
NRR Supplement and AEOD Supplement

Dear Mr. Martin:

Systematic Assessment of Licensee Performance (SALP)

The Omaha Public Power District received References 2 and 3 which contained the SALP Board Report for the period of September 1, 1983 through February 28, 1985. The SALP Report stated that the overall performance of the Fort Calhoun Station indicates a high level of dedication to nuclear safety as well as a high degree of technical competence in diverse areas essential to the safe operation of the facility. The SALP review covered 11 functional areas related to the Fort Calhoun Station operation and design. The SALP report detailed findings and assigned a performance rating to each functional area. OPPD appreciates this feedback on our performance and the assignment of Category I ratings in seven of these eleven functional areas. The attached provides our formal response to this SALP report in the functional areas of security/safeguards and training as you required.


Sincerely,



R. L. Andrews
Division Manager
Nuclear Production Division

RLA/JJF:glp
Enclosure

cc: LeBoeuf, Lamb, Leiby & MacRae
1333 New Hampshire Avenue, N.W.
Washington, D.C. 20036

6/23/85

Mr. E. G. Tourigny
NRC Project Manager

Mr. L. A. Yandell
NRC Senior Resident Inspector

1E40

Attachment

OMAHA PUBLIC POWER DISTRICT'S RESPONSE TO
SALP FINDINGS AND RECOMMENDATIONS

A. SECURITY AND SAFEGUARDS

Recommendation

The level of licensee management attention evidenced during the last quarter of the SALP period should be continued.

The licensee should increase audit activity of security training, maintenance, and requirements of the security plan. Licensee management should ensure that security resources and organization are adequate to implement the security plan.

Response

The District intends to continue the management attention that has been given to security in the last quarter of the SALP report period. The District has submitted a variety of correspondence to the Commission which delineates the actions which have and will be taken to correct apparent non-compliances generated as a result of the Commission's security inspections. Additional emphasis has also been placed on more timely resolution of OPPD identified weaknesses in the security program. Effective implementation of the Physical Security Plan will continue to be emphasized and resources will be committed as necessary to ensure this objective is met.

The SALP report indicated that a number of Licensee Event Reports were submitted by OPPD during this evaluation period relative to security system failures. OPPD reported these as Physical Security Event reports pursuant to 10 CFR 73.71 not as Licensee Event Reports pursuant to 10 CFR 50.73. Previously OPPD provided the NRC with an action plan to reduce the number of reportable security system failures. OPPD believes that this action plan will result also in a more reliable security system.

B. TRAINING

Recommendation

Licensee management should provide aggressive action to ensure control of the training program in order to maintain the positive trend that appears to have been established toward the end of this evaluation period. The effort at upgrading lesson plans and student material needs to be carried through to completion. The need for an expanded training staff remains and this shortcoming should be resolved as soon as possible. The licensee should further consider the benefits of obtaining access to a site-specific simulator for training of the Fort Calhoun Station operators.

The quality of instructors should be evaluated and training provided as required to increase the effectiveness of the training staff. Training in the areas of security, chemistry, and radiation protection needs to be better coordinated and administered under the training department.

Response

The Omaha Public Power District recognizes the need to strengthen the Fort Calhoun Station training program. We are committed to developing a strong training organization and program and to the achievement of INPO accreditation for our program.

This recognition has resulted in a comprehensive review of the training organization and the development of a plan to strengthen the existing organization. This plan is currently in the implementation phase and significant improvements are expected this year.

OPPD will aggressively pursue filling authorized, but as yet unfilled, training staff positions to reduce the reliance on contracted training personnel.

In summary, OPPD plans on significant improvements in both these functional areas. I anticipate and expect these improvements.

M. Andrews