

2012-0220

1

**RESPONSE TO FREEDOM OF
INFORMATION ACT (FOIA) / PRIVACY
ACT (PA) REQUEST**

RESPONSE
TYPE

FINAL

PARTIAL

REQUESTER

Amita Sharma

DATE

JUL 24 2012

PART I. -- INFORMATION RELEASED

- No additional agency records subject to the request have been located.
- Requested records are available through another public distribution program. See Comments section.
- | |
|-----------------|
| APPENDICES
A |
|-----------------|

 Agency records subject to the request that are identified in the listed appendices are already available for public inspection and copying at the NRC Public Document Room.
- | |
|------------|
| APPENDICES |
|------------|

 Agency records subject to the request that are identified in the listed appendices are being made available for public inspection and copying at the NRC Public Document Room.
- Enclosed is information on how you may obtain access to and the charges for copying records located at the NRC Public Document Room, 11555 Rockville Pike, Rockville, MD 20852-2738.
- | |
|-----------------|
| APPENDICES
B |
|-----------------|

 Agency records subject to the request are enclosed.
- Records subject to the request that contain information originated by or of interest to another Federal agency have been referred to that agency (see comments section) for a disclosure determination and direct response to you.
- We are continuing to process your request.
- See Comments.

PART I.A -- FEES

AMOUNT *

\$ 0.00

You will be billed by NRC for the amount listed.

None. Minimum fee threshold not met.

You will receive a refund for the amount listed.

Fees waived.

* See comments for details

PART I.B -- INFORMATION NOT LOCATED OR WITHHELD FROM DISCLOSURE

- No agency records subject to the request have been located.
- Certain information in the requested records is being withheld from disclosure pursuant to the exemptions described in and for the reasons stated in Part II.
- This determination may be appealed within 30 days by writing to the FOIA/PA Officer, U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001. Clearly state on the envelope and in the letter that it is a "FOIA/PA Appeal."


PART I.C COMMENTS (Use attached Comments continuation page if required)

The incoming request is located in ADAMS at ML12129A064

Records with a ML Accession Number are publicly available in the NRC's Public Electronic Reading Room at <http://www.nrc.gov/reading-rm.html>. If you need assistance in obtaining these records, please contact the NRC's Public Documents Room (PDR) at 301-415-4737, or 1-800-397-4209, or by E-mail to PDR.Resource@nrc.gov.

SIGNATURE - FREEDOM OF INFORMATION ACT AND PRIVACY ACT OFFICER

Donna L. Sealing



**APPENDIX A
RECORDS ALREADY PUBLICLY AVAILABLE**

<u>NO.</u>	<u>DATE</u>	<u>ACCESSION NUMBER</u>	<u>DESCRIPTION/ (PAGE COUNT)</u>
1.	05/25/06	ML061450255	Forthcoming Meeting with Southern California Edison to discuss steam generator replacement plan. (5 pages)
2.	06/07/06	ML121350603	Southern California Edison Slides on Steam Generator Replacement Project Overview. (22 pages)
3.	06/16/06	ML061670140	Summary of Meeting with Southern California Edison on overview of the steam generator replacement project. (6 pages)
4.	09/02/09	ML092440095	Forthcoming Meeting Notice with Southern California Edison Company to discuss the root cause and corrective actions for the divider plate weld defects. (4 pages)
5.	09/09/09	ML092520553	Revised Forthcoming Meeting Notice with Southern California Edison Company. (4 pages)
6.	09/10/09	ML092600513	Report on Replacement Steam Generator Divider Plate Weld Joint Separation Root Cause Evaluation, (pages 1 thru 101). (101 pages)
7.	09/10/09	ML092600515	Report on Replacement Steam Generator Divider Plate Weld Joint Separation Root Cause Evaluation, (pages 101 thru 145). (45 pages)
8.	09/10/09	ML092600516	Report on Replacement Steam Generator Divider Plate Weld Joint Separation Root Cause Evaluation, (pages 146 thru 484). (339 pages)
9.	09/11/09	ML092600514	Letter from A. Scherer, SCE to NRC enclosing the Root Cause Evaluation Divider Plate Weld Joint Separation in the Replacement Steam Generators, San Onofre Nuclear Generating Station, Unit 3. (8 pages)
10.	09/15/09	ML092590470	Southern California Edison Slides on Divider Plate-to-Channel Head Weld Separation. (29 pages)
11.	09/25/09	ML092440095	Summary of September 15, 2009, Meeting with SCE on Weld Defects found in the Replacement Steam Generators intended for Future use at San Onofre Unit 3. (5 pages)

12. 11/13/09 ML093070450 Letter from Juan Peralta, NRO to S. Kureishi, Sumitomo Metal Industries on NRC Inspection Report No. 99901384/2009-201 (Notice of Nonconformance). (22 pages)
13. 12/07/09 ML093430116 Letter from R. St. Onge, SCE to NRC on Inspection of Divider Plate Weld Joint in the Replacement Steam Generators, San Onofre Units 2 and 3. (2 pages)

**APPENDIX B
RECORDS BEING RELEASED IN THEIR ENTIRETY
(If copyrighted identify with *)**

<u>NO.</u>	<u>DATE</u>	<u>DESCRIPTION/ (PAGE COUNT)</u>
1.	Undated	San Onofre Nuclear Generating Station Provides Status Update, 1 page