



UNIVERSITY OF MISSOURI

Research Reactor Facility

Research Park  
Columbia, Missouri 65201  
Telephone (314) 882-4211

November 28, 1978

Directorate of Licensing  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20545

Subject: Renewal of Senior Reactor  
Operator License No. 2862

Dear Sir:

I wish to submit the following information in accordance with N.R.C. Regulation 10 CFR, Chapter 1, Part 55, for renewal of Senior Reactor Operator License No. 2862 for the University of Missouri Research Reactor at Columbia, Missouri.

Name: Walter Armurthur Meyer, Jr.

Citizenship: United States of America

Age: (b)(6)

Address: (b)(6)

Education: (b)(6)

781220004

82



Directorate of Licensing


Page 2

Experience: December 1971 to May 1974 - Reactor Operator aboard  
U.S.S. Tautog (SSN 639)

September 9, 1975 to January 1977 - Reactor Operator  
(License No. OP-3896) at the University of Missouri  
Research Reactor Facility. I have participated in  
all reactor routine evolutions (weekly startups and  
shutdowns, operation of reactor associated systems,  
refueling, fuel handling and inspections, reactor  
system compliance checks, normal preventive mainte-  
nance). Approximately 40% of my eight hour shift  
time is spent as console operator.

January 1977 to Present - Performing duties of Senior  
Reactor Operator.

Sincerely,



Walter A. Meyer, Jr.  
Senior Reactor Operator

WAM:vs