

## Ryder, Christopher

---

**From:** Thomas, MaryLynne  
**Sent:** Wednesday, August 15, 2012 4:55 PM  
**To:** Adams, Mary; Ryder, Christopher  
**Subject:** FW: Inspection Status

FYI

**From:** Prince, Robert  
**Sent:** Wednesday, August 15, 2012 4:39 PM  
**To:** Thomas, MaryLynne; Sykes, Marvin  
**Cc:** Blamey, Alan  
**Subject:** Inspection Status

As of COB Wednesday we have no issues in the three inspection modules - ENV, RWM and T. Exit is scheduled for 4:00 p.m. on Thursday.

Regarding the two ground water monitoring wells that were "relocated". The old wells were either damaged or it took an extended period of time to collect a water sample. Well 13 they believed calapsed or otherwise became blocked. Attempts to unclog the well were unsuccessful. Well 23 is simply difficult to withdraw or pump a sample of water from. The new well is also slow when obtaining a sample.

The two new wells for each location are located approximately 3'-4' from the old well and were drilled to the same location.

There was an opportunity to observe several waste/product shipments during the week - so that area is getting a good review.

Bob