

NRC INSPECTION MANUAL

DIRS

Change Notice 12-018

DELETED:

	<u>Number</u>	<u>Date</u>
1.	IMC 1245C10	12/29/11
2.	IP 71111.11	12/06/11
3.		
4.		

TRANSMITTED:

	<u>Number</u>	<u>Date</u>
	IMC 1245C10	08/27/12
	IP 71111.11	08/27/12

TRAINING: No.

REMARKS: IMC 1245 App C10, "Operator Licensing (OL) Examiner Technical Proficiency Training and Qualification Journal," has been revised to remove the requirement that requalification inspections must be lead by examiners also qualified as a Reactor Operations Inspector. The latest revision of IP 71111.11 states who can lead requalification inspections.

IP 71111.11, "Licensed Operator Requalification Program and Licensed Performance," has been revised to correct minor typographical errors, clarify who can perform the biennial inspection, add references to industry standards for requalification examinations, change wording of appendices, and remove the number of licensee evaluators used during scenarios as a metric from Appendix D.

DISTRIBUTION: Standard

END