

CONVERSATION RECORD
(time) (date)

TIME DATE
8/2/12

VISIT

CONFERENCE

TELEPHONE

INCOMING

OUTGOING

NAME OF PERSON(S) CONTACTED OR IN CONTACT
Regis Greenwood, RSO

ORGANIZATION (OFFICE, DEPT. ETC.)
ARC

TELEPHONE NO.
314-991-4545

SUBJECT

C/N 577564

SUMMARY

This pertains to ARC's 8/2/12 reply to my 8/1/12 request for additional information. Specifically, I requested clarification of the following.


1. Describe what is meant by "intermittent HP coverage" that was part of your response to question no. 4.
2. It is our understanding that ARC staff will remove contaminated roofing material, to the best extent possible, before contract workers are allowed to initiate work. Please confirm.
3. Explain why contract roofing workers will not be provided coveralls while they perform work on the roofs.
4. Describe instrumentation that will be used to frisk contract roofers.

ACTION REQUIRED

Submit response to the request for add'l info noted above.

NAME OF PERSON DOCUMENTING CONVERSATION
Kevin Null

SIGNATURE



DATE
8/2/12

ACTION TAKEN

SIGNATURE

TITLE

DATE