

Docket File Information
SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED: Michael Lala, M.D., P.C South Allen Radiology 3815 Pine Harbor Drive West Bloomfield, MI 48323 REPORT NUMBER(S) 2012-001	2. NRC/REGIONAL OFFICE Region III U. S. Nuclear Regulatory Commission 2443 Warrenville Road, Suite 210 Lisle, IL 60532-4352
---	---

3. DOCKET NUMBER(S) 030-18558	4. LICENSE NUMBER(S) 21-24380-01	5. DATE(S) OF INSPECTION Aug. 28 - Sept. 5, 2012
--------------------------------------	---	---

6. INSPECTION PROCEDURES USED 87130 & 87131	7. INSPECTION FOCUS AREAS 03.01 -03.07
--	---

SUPPLEMENTAL INSPECTION INFORMATION

1. PROGRAM CODE(S) 02200	2. PRIORITY 3	3. LICENSEE CONTACT Michael Lala, M.D., RSO	4. TELEPHONE NUMBER (248) 225-6909
---------------------------------	----------------------	--	---

Main Office Inspection Next Inspection Date: September 2015

Field Office Inspection 26699 W. 12 Mile Road, Southfield, MI

Temporary Job Site Inspection

PROGRAM SCOPE

This licensee was a private practice out-patient diagnostic clinic authorized to use material permitted by Sections 35.100, 35.200, and 35.300; the licensee only performed cardiac studies at the time of this inspection. Radioiodine had not been used since the previous inspection. The licensee operated two clinics in the suburban Detroit area; the Livonia office was expected to initiate activities within a few months. The licensee employed one part-time technologist at its Southfield location. The clinic administered approximately 3-4 diagnostic cardiology procedures every Tuesday. The licensee received unit doses from a licensed radiopharmacy. The licensee retained the services of a consulting physicist who audited the radiation safety program on a quarterly basis (last September 4, 2012, with no violations or unusual findings).

This inspection consisted of interviews with licensee personnel, a review of selected records, a tour of the nuclear medicine department, and independent measurements. At the time of this inspection, the licensee was in the process of obtaining new imaging equipment and no studies were conducted. This inspection included in-office review through September 5, 2012, to review a sampling of the consultant's program audit reports which could not be located during the on-site inspection.

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED: Michael Lala, M.D., P.C South Allen Radiology 3815 Pine Harbor Drive West Bloomfield, MI 48323 REPORT NUMBER(S) 2012-001		2. NRC/REGIONAL OFFICE Region III U. S. Nuclear Regulatory Commission 2443 Warrenville Road, Suite 210 Lisle, IL 60532-4352	
3. DOCKET NUMBER(S) 030-18558	4. LICENSE NUMBER(S) 21-24380-01	5. DATE(S) OF INSPECTION Aug. 28 - Sept. 5, 2012	

LICENSEE:

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:



- 1. Based on the inspection findings, no violations were identified.
- 2. Previous violation(s) closed.
- 3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, to exercise discretion, were satisfied.

Non-cited violation(s) were discussed involving the following requirement(s):

- 4. During this inspection, certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited in accordance with NRC Enforcement Policy. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.
(Violations and Corrective Actions)

Statement of Corrective Actions

I hereby state that, within 30 days, the actions described by me to the Inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

TITLE	PRINTED NAME	SIGNATURE	DATE
LICENSEE'S REPRESENTATIVE			
NRC INSPECTOR	Deborah A. Piskura, Health Physicist		9/5/12
BRANCH CHIEF	Tamara E. Bloomer, Chief, MIB		9/6/12