

**History of Steam Generators
 Indian Point Unit 2 and Unit 3**

	IP2 (DPR-26)*	IP3 (DPR-64)**
Date of Initial 40-yr. Operating License	9/28/1973	12/12/1975
Date of Installation of Replacement Steam Generators at IP Unit 3	--	6/1989
Date of Tube Rupture of IP Unit 2 Steam Generator	2/15/2000	--
Date of Installation of Replacement Steam Generators at IP Unit 2	12/2000	--
Date of Expiration of 40-yr. Operating license	9/28/2013	12/12/2015
Years of Operations of Replacement Steam Generators at Expiration of 40-yr. Operating License	12.8 years	26.5 years

***Sources:**

Appendix A, Volume 23, NUREG-1350, 2011-2012 Information Digest, August 2011 (NRCR00086)

Indian Point Unit 2, NL-00-043. Letter from J. Baumstark, Consolidated Edison Company of New York to NRC, "Root Cause Evaluation for Steam Generator Tube Rupture Event of February 15, 2000," Apr. 14, 2000 (ENT000567)

NRC OIG, NRC's Response to the February 15, 2000 Steam Generator Tube Rupture at Indian Point Unit 2 Power Plant, Case No. 00-03S (Aug. 29, 2000) (NYS000457)

K. Karwoski to M. Khanna October 8, 2009 email and chart, Steam Generator Replacements Completed (NYS000458)

****Sources:**

Appendix A, Volume 23, NUREG-1350, 2011-2012 Information Digest, August 2011 (NRCR00086)

History of Westinghouse Model 44 Steam Generators (NYS000378)

K. Karwoski to M. Khanna October 8, 2009 email and chart, Steam Generator Replacements Completed (NYS000458)