



UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION I
2100 RENAISSANCE BOULEVARD, SUITE 100
KING OF PRUSSIA, PENNSYLVANIA 19406-2713

November 19, 2012

Docket No. 03013146

License No. 06-17669-01

Harry Agahigian, Ph.D.
President and Laboratory Director
Baron Consulting
273 Pepe's Farm Road
Milford, CT 06460

SUBJECT: NRC INSPECTION REPORT NO. 03013146/2012001, BARON CONSULTING

Dear Dr. Agahigian:

This letter refers to your October 17, 2012, correspondence, in response to our September 17, 2012, letter. Thank you for informing us of the corrective and preventive actions documented in your letter. These actions will be examined during a future inspection of your licensed program

Item 3 of your October 17, 2012, letter states that you will notify us whenever the electron capture detector (ECD) is replaced by the manufacturer. Please note that the ECDs in use at the time of the inspection are not specifically licensed, and thus, no additional notification would be required for this license unless you start using specifically licensed ECDs again. You currently are using generally licensed ECDs and as required by 10 CFR 31.5(c)(15) may not hold devices that are no longer usable for longer than 2 years.

Your cooperation with us is appreciated.

Sincerely,

Original signed by Judith A. Joustra

Judith A. Joustra, Chief
Commercial and R&D Branch
Division of Nuclear Materials Safety

cc:
Barbara A. L. Obert, Radiation Safety Officer
State of Connecticut

November 19, 2012

Docket No. 03013146

License No. 06-17669-01

Harry Agahigian, Ph.D.
President and Laboratory Director
Baron Consulting
273 Pepe's Farm Road
Milford, CT 06460

SUBJECT: NRC INSPECTION REPORT NO. 03013146/2012001, BARON CONSULTING

Dear Dr. Agahigian:

This letter refers to your October 17, 2012, correspondence, in response to our September 17, 2012, letter. Thank you for informing us of the corrective and preventive actions documented in your letter. These actions will be examined during a future inspection of your licensed program

Item 3 of your October 17, 2012, letter states that you will notify us whenever the electron capture detector (ECD) is replaced by the manufacturer. Please note that the ECDs in use at the time of the inspection are not specifically licensed, and thus, no additional notification would be required for this license unless you start using specifically licensed ECDs again. You currently are using generally licensed ECDs and as required by 10 CFR 31.5(c)(15) may not hold devices that are no longer usable for longer than 2 years.

Your cooperation with us is appreciated.

Sincerely,

Original signed by Judith A. Joustra

Judith A. Joustra, Chief
Commercial and R&D Branch
Division of Nuclear Materials Safety

cc:
Barbara A. L. Obert, Radiation Safety Officer
State of Connecticut

DOCUMENT NAME: G:\WordDocs\Current\Insp Letter\L06-17669-01.2012001.doc

ML12324A256

SUNSI Review Complete: DLawyer

After declaring this document "An Official Agency Record" it will be released to the Public.

To receive a copy of this document, indicate in the box: "C" = Copy w/o attach/encl "E" = Copy w/ attach/encl "N" = No copy

OFFICE	DNMS/RI	N	DNMS/RI	DNMS/RI		
NAME	DLawyer/dl		JJoustra/jj			
DATE	11/19/2012		11/19/12			

OFFICIAL RECORD COPY